

Phone: (763) 255-2555

(800) 328-5454

FAX: (763) 255-2530



3787 95th Ave. N.E.

Blaine, MN 55014

info@arrowheadep.com

www.arrowheadep.com

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS



ADR0329

**For CS130D SERIES;
12-VOLT; 105 AMP;**

11:00 Plug Position;

LESTER 8296;

PIC 240-6128;

Used on:

2003 Honda Accord w/3.0L

**REPL.: DELCO
10480497;
HONDA
31100-RCA-A01**



AFD0128

**For 6G SERIES;
12-VOLT; 135 AMP;**

LESTER 8303;

PIC 250-432;

NOTE: CLUTCH PULLEY INCLUDED

Used on:

2003-04 Ford Expedition w/4.6L, 5.4L

2003-04 Lincoln Navigator w/5.4L

**REPL.: FORD
3L74-10300-AA, -BA,
3L74-10300-BB,
3L74-10346-AA, -BA
3L7Z-10346-AA, -BA**



AH10098

**IR/EF;
24-VOLT; 25 AMP;**

LESTER 12324;

PIC 204-204;

Used on Nissan Lift Trucks

**REPL.: HITACHI
LR225-84T;
NISSAN
23100-51H00**



AMT0048

**IR/IF;
12-VOLT; 75 AMP;**

LESTER 13752;

PIC 203-306;

Used on:

1998 Subaru Forester w/2.5L

1997 Subaru Impreza w/1.8L

1997-98 Subaru Impreza w/2.2L

1998 Subaru Impreza w/2.5L

**REPL.: MITSUBISHI
A2TA7691;
SUBARU
23700-AA290**



ADR0346

**For AD230 SERIES;
12-VOLT; 105 AMP;**

12:00 Plug Position;

LESTER 8289;

PIC 240-6125B;

Used on:

2003-04 Buick Regal w/3.8L

2003-04 Chevrolet Impala w/3.8L

2003-04 Chevrolet Monte Carlo w/3.8L

**REPL.: DELCO
10333166**



AHA4006

**STATOR COIL,
For HONDA M/C,**

PIC 7299-2006;

Used on HONDA:

VF700S 1984-85

VF750S 1982-83

VF1100C 1983-86

VF1100S 1984-85

**REPL.: HONDA
31120-MB0-005,
31120-MB0-015,
31120-MB0-025,
31120-MB0-405,
31120-MB0-415**



AMT0043

**IR/IF;
12-VOLT; 75 AMP;**

LESTER 13479;

PIC 203-305;

Used on:

1993-97 Subaru Impreza w/1.8L

1995-96 Subaru Impreza w/2.2L

**REPL.: MITSUBISHI
A2T39091;
SUBARU
23700-AA202**



AMT0102

**IR/IF;
12-VOLT; 75 AMP;**

LESTER 13451;

PIC 203-331;

Used on:

1993-94 Dodge Colt w/2.4L

1993-96 Eagle Summit w/2.4L

1992-95 Mitsubishi Expo w/2.4L

1994-95 Mitsubishi Galant w/2.4L

1993-94 Plymouth Colt w/2.4L

**REPL.: MITSUBISHI
A2T38391, -81791;
MITSUBISHI MOTORS
MD190819, -8164**

Phone: (763) 255-2555

(800) 328-5454

FAX: (763) 255-2530



3787 95th Ave. N.E.

Blaine, MN 55014

info@arrowheadep.com

www.arrowheadep.com

The information herein is based upon data which we believe to be correct and believe to have been obtained from reliable sources, but no representation is made herein, nor should any be implied, regarding the accuracy of any such information and we assume no liability for any errors or omissions in any such information. Any original equipment manufacturers or other manufacturers or distributors, whose names, numbers, pictures, symbols, products and/or descriptions are, or may be, listed or shown herein are used for reference purposes only and there is no representation made or intended, nor should any be implied, that any item reference herein is the product of, or was manufactured and/or distributed, by, the referenced manufacturer or distributor, as the case may be.
This brochure is intended for reference purposes only. For pricing or terms and conditions, please refer to your price sheet.

9/09-II

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS



AMT0115 IR/IF; 12-VOLT; 65 AMP;

LESTER 13478;
PIC 203-429, -A;
Used on:
1993-97 Infiniti J30 w/3.0L
1994-96 Nissan 300ZX w/3.0L

REPL.: MITSUBISHI
A2T33593, -A, -B, -C;
NISSAN
23100-0P513, -5, -6



AMT0165 IR/IF; 12-VOLT; 85 AMP;

LESTER 13898;
PIC 203-472;
Used on:
2000-03 Mitsubishi Galant w/2.4L

REPL.: MITSUBISHI
A2TB5791;
MITSUBISHI MOTORS
MD368519



SBO0189 PMGR; 12-VOLT; CCW; 10-TOOTH

LESTER 17970; PIC 120-449;
Used on:
2006-08 Audi A3 w/2.0L
2006-07 Volkswagen Golf w/2.0L
2006-08 Volkswagen Jetta w/2.0L
2006-08 Volkswagen Passat w/2.0L

REPL.: BOSCH
0-001-121-402, -3;
VOLKSWAGEN
02M-911-023G



SDR0295 FOR 41MT SERIES, DD; 12-VOLT; CW; 12-TOOTH

LESTER 6613; PIC 141-373A;
Used on Heavy-Duty Trucks

REPL.: DELCO
10461171, 10461227,
10478999



SMT0152 PMGR; 12-VOLT; CW; 10-TOOTH

LESTER 17799; PIC 103-221;
Used on:
2000-01 Dodge Dakota w/2.5L
2001-02 Jeep Wrangler w/2.5L

REPL.: MITSUBISHI
MOT83381;
CHRYSLER
56041013AC



SMU0305 FOR YAMAHA M/C, 12-VOLT;

LESTER 18748;
PIC 191-380, -A;

Used on:
1999 XV1100 VIRAGO 1063CC
2008-04 XVS11 V-STAR CUSTOM 1063CC
2008-04 XVS11A V-STAR CLASSIC 1063CC
2007-04 XVS11A V-STAR SILVER 1063CC
2003-99 XVS1100 V-STAR CLC. 1063CC
2003-99 XVS1100 V-STAR CUST 1063CC
2003 XVS1100 V-STAR SILVER 1063CC

REPL.: YAMAHA
5EL-81890-00-00,
5EL-81890-01-00



SMU0310 PMOSGR; 12-VOLT; CW; 9-TOOTH

LESTER 17675;
PIC 191-157;
Used on:
1996-98 Honda Civic HX w/1.6L

REPL.: MITSUBA
SM422-08;
HONDA
31200-P2M-J61



SND0243 FOR THERMO-KING, OSGR; 12-VOLT; CW; 9-TOOTH

LESTER 17373; PIC 190-209, -289;
Used on Thermo King

REPL.: DENSO
128000-0570, -2280;
CARRIER
30-00308-01, -2;
THERMO KING
45-1170



SND0453 FOR HONDA SMALL ENGINES, DD; 12-VOLT; CCW; 10-TOOTH

LESTER 19610; PIC 190-6074;
Used on Honda GXV530 V-Twin

REPL.: DENSO
228000-9480;
HONDA
31200-Z0A-003,
DDWDN



SND0585 FOR SKI-DOO SNOWMOBILES, PMDD; 12-VOLT;

LESTER 18873; PIC 190-6183;
Used on 1985-2000 Ski-Doo Snowmobiles
w/248cc and 494cc Engines

REPL.: DENSO
128000-1670, -1;
BOMBARDIER
410-207-500, 995430