



NEW PRODUCTS

MAIN LOCATION 800.328.5454 | WEST COAST 800.457.1728 | CANADA 877.617.2888

AG / INDUSTRIAL



AIA0034
For Case, New Holland
IR/IF: 12-Volt: 150 Amp;
Lester 23842;
PIC 282-664;

10-Groove Pulley
USED ON:
Case Tractors
07-On Puma 165/180/195/210 w/6-411 Dsl
New Holland Tractors
07-On T7030 w/6.75L 6cyl 165HP Dsl
07-On T7040 w/6.75L 6cyl 180HP Dsl
07-On T7050 w/6.75L 6cyl 195HP Dsl
07-On T7060 w/6.75L 6cyl 210HP Dsl

REPLACES:
LETRIKA
IA 1198;
CASE
87573243;
MAHLE
MG30;
NEW HOLLAND
84141455, 87573243;



AIA0040
For Marshall, Steyr
IR/EF: 12-Volt: 33 Amp;
Lester 12685;
PIC 220-5421, 282-303;

1-V Pulley 68mm OD
Clock Position 11
USED ON:
Marshall and Steyr Applications

REPLACES:
LETRIKA IA 0062;
AGCO C000900010220;
BOSCH 0-120-339-526;
MAHLE MG371;
STEYR
30800090021, 308 00 09 0021;



AND0644
For Komatsu
IR/IF: 12-Volt: 120 Amp;
Lester 20788;
PIC 290-5787;

8-Groove Pulley 77mm OD
Clock Position 6
Plug P-IG-L
USED ON:
Komatsu Applications

REPLACES:
DENSO
102211-3290;
KOMATSU
600-861-1930;

AUTO



ABO0398
For Mercedes Benz
IR/IF: 12-Volt: 220 Amp;
Lester 11445;
PIC 220-5498;

7-Groove Clutch Pulley
USED ON:
2011-13 E350 w/3.0L Dsl
2010-12 GL350 w/3.0L Dsl
2009-11 ML350 w/3.0L Dsl
2010-12 R350 w/3.0L Dsl

REPLACES:
BOSCH
0-121-813-020, -120;
MERCEDES BENZ
014-154-13-02;

AUTO



AB00410
For Mercedes Benz
IR/IF: 12-Volt; 220 Amp;
Lester 11304;
PIC 220-5595;

7-Groove Pulley 50mm OD
 Clock Position 1

USED ON:
 2010-14 CL600 w/5.5L V12 2006-13 S600 w/5.5L
 2008-14 CL65 AMG w/6.0L 2007-13 S65 AMG w/6.0L
 2012-13 S350 w/3.0L Dsl

REPLACES:
BOSCH
 0-121-813-002, -102;
MERCEDES BENZ
 013-154-06-02,
 A013-154-06-02;



ALU0033
For MGB
IR/EF: 12-Volt; 43 Amp;
Lester 14050;
PIC 280-100;

1-V Pulley

USED ON:
 1974-78 MGB w/1.8L

REPLACES:
LUCAS
 23746, -49, -56, 23806, -32,
 -32A/B, -49, -92;



AND0352
For Lincoln
IR/IF: 12-Volt; 140 Amp;
Remanufactured;
Lester 11000;
PIC 290-5091, -5289;

6-Groove Pulley 60mm OD S-L-AM Plug
 Clock Position 12

USED ON:
 2003-05 Lincoln LS w/3.0L V6

REPLACES:
DENSO
 104210-3210, -3213, -4160;
FORD
 3W4T-10300-BF, -BH,
 3W4Z-10346-BA,
 4W4T-10300-BA;
MOTORCRAFT
 GL-536;



AND0617
For Hyundai
IR/IF: 12-Volt; 130 Amp;
Lester 11494;
PIC 290-5495;

6-Groove Pulley 52.5mm OD
 Clock Position 10

USED ON:
 2009 Hyundai Genesis w/3.8L
 2010-16 Hyundai Gensis Coupe w/3.8L

REPLACES:
POONG SUNG
 02131-9530;
HYUNDAI
 37300-3C180;



AVA0139
For Chevrolet
IR/IF: 12-Volt; 130 Amp;
Lester 11654;
PIC 208-5043A, 208-896;

5-Groove Clutch Pulley 53mm OD
 Clock Position 12

USED ON:
 2012-15 Cruze w/1.4L L4
 2016 Cruze Limited w/1.4L L4

REPLACES:
VALEO
 FG12S054, -65;
GENERAL MOTORS
 13588290, 95939944;



SMT0352
For Mitsubishi
PMGR: 12-Volt;
CW: 9-Tooth;
Lester 19105;
PIC 103-5141;

USED ON:
 2008-16 Mitsubishi Lancer w/2.0L Turbo

REPLACES:
MITSUBISHI
 MOT22871;
MITSUBISHI MOTORS
 1810A123;

AUTO



VND0257
For Acura, Honda
IR/IF: 12-Volt; 105 Amp;
Remanufactured;
Lester 11503, 13980;
PIC 290-5096, -A, -C;

Premium Alternator
 7-Groove Pulley 60mm OD
 Square C-FR-IG-L Plug
 Side Mounting - 2 Bottom Mounts
 Plug at 10:00 - B+ at 12:00

USED ON:
 Acura
 2004-08 TSX w/2.4L
 Honda
 2003-07 Accord w/2.4L
 2006-11 Civic w/2.0L
 2007-11 CR-V w/2.4L
 2003-11 Element w/2.4L

REPLACES:
DENSO
 104210-3290, -3291, -3292,
 -3293, -4730, -4731, -4732;
ACURA
 31100-RAA-A01, 31100-RTA-
 003, -13, -23, -33;
HONDA
 31100-RAA-A01, -3, -4, -5,
 31100-RTA-003, -13, -23, -33
 CSC29, CSD73;



VND0265
For Dodge Light Trucks
ER/IF: 12-Volt; 160 Amp;
Remanufactured;
Lester 13988;
PIC 290-5139, -A;

Premium Alternator
 7-Groove Pulley 55.5mm OD (Rib)
 Clock Position 10

USED ON:
 2004-06 Dodge Durango w/5.7L
 2003-06 Dodge RAM Pickups w/5.7L

REPLACES:
DENSO
 421000-0210, -12, -80, -81, -82;
CHRYSLER
 56028697AA, -D;



VND0281
For Dodge Light Trucks,
Jeep
ER/IF: 12-Volt; 160 Amp;
Remanufactured;
Lester 13913;
PIC 290-5133;

Premium Alternator
 6-Groove Pulley
 Clock Position 2

USED ON:
 2004-06 Dodge Durango w/3.7L
 2001-06 Dodge Durango w/4.7L
 2006 Jeep Commander w/3.7L, 4.7L
 2005-06 Jeep Grand Cherokee w/3.7L
 2005-06 Jeep Grand Cherokee w/4.7L
 2003-06 Jeep Liberty w/3.7L

REPLACES:
DENSO
 421000-0040, -2, -3, -4;
CHRYSLER
 4801252AA, 5170748AA,
 56029914AA, -AE;



VND0288
For Scion, Toyota
IR/IF: 12-Volt; 100 Amp;
Remanufactured;
Lester 11034, 11088;
PIC 290-5153, 290-5155,
-A, -C;

Premium Alternator
 7-Groove Pulley 60mm OD
 Square S-IG-L-M Plug

USED ON:
 2005-10 Scion TC w/2.4L
 2004-06 Toyota Camry w/2.4L
 2004-07 Toyota Highlander w/2.4L
 2004-05 Toyota RAV4 w/2.4L
 2004-08 Toyota Solara w/2.4L

REPLACES:
DENSO
 104210-3780, -3880, -3890,
 -5330;
TOYOTA
 27060-0H100, -28260,
 -28270, -28350;



VND0289
For Toyota
IR/IF: 12-Volt; 150 Amp;
Remanufactured;
Lester 13981;
PIC 290-5092;

Premium Alternator
 6-Groove Pulley 57mm OD
 Clock Position 2
 Square S-IG-L-M Plug

USED ON:
 2003-06 Toyota Sienna w/3.3L

REPLACES:
DENSO
 104210-3450;
TOYOTA
 27060-0A110;

AUTO



VND0291
For GM
IR/IF: 12-Volt: 140 Amp;
Remanufactured;
Lester 11035;
 PIC 290-5179, -A;

Premium Alternator
 6-Groove Pulley 62mm OD
 S-F-L Plug
USED ON:
 2004-05 Buick LeSabre w/3.8L
 2004-05 Pontiac Bonneville w/3.8L

REPLACES:
DENSO
 104210-3300, -4540;
GENERAL MOTORS
 15145637, 25758348;



VND0294
For Lexus, Toyota
IR/IF: 12-Volt: 130 Amp;
Remanufactured;
Lester 11032;
 PIC 290-5190, -A, -C;

Premium Alternator
 6-Groove Pulley 57mm OD
 Square S-IG-L-M Plug
USED ON:
 2004-06 Lexus RX330 w/3.3L
 2003-07 Toyota Sienna w/3.3L

REPLACES:
DENSO
 104210-3480, -650, -651,
 -652, -660, -661, -662, -750,
 -751;
TOYOTA
 27060-0A100, -0A130,
 -20280, -20290;



VND0295
For Dodge Light Trucks
ER/IF: 12-Volt: 136 Amp;
Remanufactured;
Lester 13912;
 PIC 290-5134, -A;

Premium Alternator
 6-Groove Pulley 57mm OD
 Clock Position 2
USED ON:
 2005-06 Dodge Durango w/3.7L
 2001-06 Dodge Durango w/4.7L
 2002-06 Dodge RAM Pickup w/3.7L
 2002-06 Dodge RAM Pickup w/4.7L

REPLACES:
DENSO
 421000-0100, -0322, -0323;
CHRYSLER
 4801251AA, 56029700AA;



VND0296
For Cadillac, Pontiac
IR/IF: 12-Volt: 140 Amp;
Remanufactured;
Lester 13919;
 PIC 290-5082, -A;

Premium Alternator
 6-Groove Pulley 62mm OD
 Clock Position 7
USED ON:
 2001-05 Cadillac DeVille w/4.6L
 2001-04 Cadillac Seville w/4.6L
 2004-05 Pontiac Bonneville w/4.6L

REPLACES:
DENSO
 104210-3060, -70;
GENERAL MOTORS
 25697765, -66, -76;



VND0297
For Acura, Honda
IR/IF: 12-Volt: 130 Amp;
Remanufactured;
Lester 13918;
 PIC 290-5084;

Premium Alternator
 6-Groove Pulley 65mm OD
 Clock Position 12
USED ON:
 2001-02 Acura MDX w/3.5L
 2002-04 Honda Odyssey w/3.5L
 2003-04 Honda Pilot w/3.5L

REPLACES:
DENSO
 104210-3090, -1, -2;
ACURA
 31100-PGK-A01, -3, CSC09;



VND0298
For Chrysler, Dodge
ER/IF: 12-Volt: 120 Amp;
Remanufactured;
Lester 13868;
 PIC 290-5120, -A;

Premium Alternator
 6-Groove Pulley 64mm OD Top Mounting Hole Round
 Clock Position 3 8mm x 1.25 B+ Stud
USED ON:
 2001-06 Chrysler Sebring w/2.4L, 2.7L L4
 2001-06 Dodge Stratus w/2.4L, 2.7L V6

REPLACES:
DENSO
 121000-2520, 421000-0060,
 -061, -062, -230, -232,
 5-121000-252;
CHRYSLER
 04606755AA, -AB, -AC, -AD,
 4606755AA, -AB, -AC, -AD;

AUTO



VND0300
For Chrysler, Dodge
IR/IF: 12-Volt; 130 Amp;
Remanufactured;
Lester 11040;
 PIC 290-5142, -3;

Premium Alternator
 4-Groove Pulley 60mm OD
USED ON:
 2003-05 Chrysler PT Cruiser w/2.4L L4
 2003-05 Dodge Neon W/2.4L L4
 2003-05 Dodge SX W/2.4L L4

REPLACES:
DENSO
 421000-0150, -151, -200,
 5-121000-348;
CHRYSLER
 56029701AB, -AD,
 56029915AB;



VND0302
For Lexus
IR/IF: 12-Volt; 130 Amp;
Remanufactured;
Lester 13992;
 PIC 290-5099;

Premium Alternator
 6-Groove Pulley 55.3mm OD
 Clock Position 12
USED ON:
 2001-03 Lexus LS430 w/4.3L
 2002-10 Lexus SC430 w/4.3L

REPLACES:
DENSO
 104210-3030, -1, -2;
TOYOTA
 27060-50280;



VND0313
For Buick
IR/IF: 12-Volt; 140 Amp;
Remanufactured;
Lester 11180;
 PIC 290-5233;

Premium Alternator
 6-Groove Pulley 63mm OD
 Clock Position 1
 Small 2-Pin L-F Plug
 6mm B+ Stud
USED ON:
 2006-08 Buick Lucerne w/3.8L V6

REPLACES:
DENSO
 104210-4360;
GENERAL MOTORS
 25764632;



VND0319
For Buick,
Chevrolet, Pontiac
IR/IF: 12-Volt; 135 Amp;
Remanufactured;
Lester 11179;
 PIC 290-5203;

Premium Alternator
 6-Groove Pulley 63mm OD
 Clock Position 12
 Small 2-Pin L-F Plug
USED ON:
 2008-09 Buick Allure w/5.3L
 2008-09 Buick LaCrosse w/5.3L
 2006-09 Chevrolet Impala w/5.3L
 2006-07 Chevrolet Monte Carlo w/5.3L
 2005-08 Pontiac Grand Prix w/5.3L

REPLACES:
DENSO
 104210-4220;
GENERAL MOTORS
 15139480;



VND0324
For Lexus
IR/IF: 12-Volt; 130 Amp;
Remanufactured;
Lester 11197;
 PIC 290-5099A;

Premium Alternator
 6-Groove Pulley 55mm OD
 Clock Position 12
 S-IG-L-M Square Plug
USED ON:
 2006-07 Lexus GS430 w/4.3L
 2004-06 Lexus LS430 w/4.3L

REPLACES:
DENSO
 1104210-4000, -1, -2;
TOYOTA
 27060-50340;



VND0327
For Land Rover
IR/IF: 12-Volt; 150 Amp;
Remanufactured;
Lester 11206;
 PIC 290-5287;

Premium Alternator
 6-Groove Pulley 53mm OD
 Clock Position 7
 LI-RC-BVS Square Plug
USED ON:
 2005-07 Land Rover LR3 w/4.4L
 2006-07 Range Rover w/4.2L, 4.4L
 2006-07 Range Rover Sport w/4.2L, 4.4L

REPLACES:
DENSO
 104210-3690;
LAND ROVER
 VLE500190;

AUTO



VND0328
For Toyota
IR/IF: 12-Volt: 130 Amp;
Remanufactured;
Lester 11084;
PIC 290-5151;

Premium Alternator
 7-Groove Pulley 60mm OD S-IG-L-M Square Plug
 Optional 130 Amp Unit
USED ON:
 2004-07 Toyota Highlander w/2.4L

REPLACES:
DENSO
 104210-4030, -2;
TOYOTA
 27060-28290;



VND0331
For Saturn
IR/IF: 12-Volt: 125 Amp;
Remanufactured;
Lester 11062;
PIC 290-5188, -A;

Premium Alternator
 6-Groove Pulley 65mm OD 4-Prong Plug
USED ON:
 2004-07 Saturn VUE w/3.5L

REPLACES:
DENSO
 104210-3770, -4310;
GENERAL MOTORS
 12582024;
HONDA
 31100-RDM-A01, CSC77;



VND0332
For Toyota
IR/IF: 12-Volt: 100 Amp;
Remanufactured;
Lester 11153;
PIC 290-5085, -5243;

Premium Alternator
 6-Groove Pulley 58mm OD Square Plug S-IG-L-M
 Clock Position 12
USED ON:
 2004-09 Toyota Tundra Pickup w/4.7L

REPLACES:
DENSO
 104210-3680, -5110;
TOYOTA
 27060-0F060, -80;



VND0339
For Acura, Honda
IR/IF: 12-Volt: 130 Amp;
Remanufactured;
Lester 11099, 11150, 11151;
PIC 290-5083, -220, -221,
-221A, -222;

Premium Alternator
 6-Groove Pulley 65mm OD C-FR-IG-L Plug
 Clock Position 11
USED ON:
 Acura Honda
 2003-06 MDX w/3.5L 2005-07 Odyssey w/3.5L
 2007-09 MDX w/3.7L 2005-08 Pilot w/3.5L
 2005-08 RL w/3.5L 2006-08 Ridgeline w/3.5L
 2004-08 TL w/3.2L
 2007-08 TL w/3.5L

REPLACES:
DENSO
 104210-3100, -4290, -4300,
 -4301, -4690;
ACURA
 31100-RDJ-A01, -GL-A01;
HONDA
 31100-RGM-A01, -JA-A01,
 -JA-A02, -YP-A01, CSD29, -30,
 -69;



VND0341
For Chrysler, Dodge
ER/IF: 12-Volt: 140 Amp;
Remanufactured;
Lester 11112;
PIC 290-5178;

Premium Alternator
 6-Groove Pulley 52mm OD
 Clock Position
USED ON:
 2005-07 Chrysler 300 Series w/2.7L, 5.7L, 6.1L
 2006-08 Dodge Charger w/2.7L, 5.7L, 6.1L
 2005-07 Dodge Magnum w/2.7L, 5.7L, 6.1L

REPLACES:
DENSO
 421000-0251, -252, -332;
CHRYSLER
 04896803AA, 4896803AA;



VND0342
For Chrysler, Dodge
ER/IF: 12-Volt: 160 Amp;
Remanufactured;
Lester 11113;
PIC 290-5176;

Premium Alternator
 6-Groove Pulley 52mm OD
 Clock Position 1
USED ON:
 2005-07 Chrysler 300 Series w/2.7L, 5.7L, 6.1L
 2006-08 Dodge Charger w/2.7L, 5.7L, 6.1L
 2005-07 Dodge Magnum w/2.7L, 5.7L, 6.1L

REPLACES:
DENSO
 421000-0260, -261, -262,
 -264, -342, -343, -344;
CHRYSLER
 4896805AA, -AB, -AC;

AUTO



VND0379
For Toyota
IR/IF: 12-Volt: 130 Amp;
Remanufactured;
Lester 13963;
PIC 290-5076;

Premium Alternator
 7-Groove Pulley 60mm OD S-IG-L Plug
 Clock Position 1
USED ON:
 2001-03 Toyota Highlander w/2.4L

REPLACES:
DENSO
 104210-3140, -1;
TOYOTA
 27060-28130;



VND0384
For Toyota
IR/IF: 12-Volt: 150 Amp;
Remanufactured;
Lester 11090;
PIC 290-5098, -A;

Premium Alternator
 7-Groove Pulley 60mm OD Square S-IG-L-M Plug
 Clock Position 12
USED ON:
 2003-09 Toyota Sequoia w/4.7L

REPLACES:
DENSO
 104210-3390, -5500;
TOYOTA
 27060-0F050, -110;



VND0389
For Dodge Light Trucks
ER/IF: 12-Volt: 160 Amp;
Remanufactured;
Lester 13915;
PIC 290-5136;

Premium Alternator
 7-Groove Pulley
 Clock Position 3
USED ON:
 2001-03 Dodge Durango w/5.9L

REPLACES:
DENSO
 421000-0051;
CHRYSLER
 56029915AA;



VND0392
For Lexus, Toyota
IR/IF: 12-Volt: 130 Amp;
Remanufactured;
Lester 11198, 13983,
13994;
PIC 290-5013, -150, -152,
-242;

Premium Alternator
 6-Groove Pulley 57mm OD Square S-IG-L-M Plug
 Clock Position 12
USED ON:
 Lexus
 2003-08 GX470 w/4.7L 2006-07 LX470 w/4.7L
 Toyota
 2003-08 4Runner w/4.7L 2003-09 Sequoia w/4.7L
 2005-07 Landcruiser w/4.7L 2003-09 Tundra w/4.7L

REPLACES:
DENSO
 104210-3380, -3440, -3441,
 -4510, -5120;
TOYOTA
 27060-0F040, -0F070,
 -50320, -50360;



VND0397
For Cadillac
IR/IF: 12-Volt: 130 Amp;
Remanufactured;
Lester 11003;
PIC 290-5158;

Premium Alternator
 6-Groove Pulley 57mm OD
USED ON:
 2003-04 Cadillac CTS w/3.2L

REPLACES:
DENSO
 104210-3280;
GENERAL MOTORS
 25738783;



VND0401
For Honda
IR/IF: 12-Volt: 130 Amp;
Remanufactured;
Lester 11030;
PIC 290-5187, -A;

Premium Alternator
 6-Groove Pulley 65mm OD Square C-FR-IG-L Plug
USED ON:
 2004-07 Honda Accord w/3.0L

REPLACES:
DENSO
 104210-3500, -4480, -4481;
HONDA
 31100-RGB-Y01, -2, CSC48,
 -50;

AUTO



VND0413
For Land Rover
IR/IF: 12-Volt: 150 Amp;
Remanufactured;
Lester 11205;
PIC 290-5286;

Premium Alternator
 6-Groove Pulley
 Clock Position 4
USED ON:
 2005-08 Landrover LR3 w/4.0L

LI-RC-BVS Plug

REPLACES:
DENSO
 104210-3700, -1;
LAND ROVER
 YLE500240, -410;



VND0416
For Chrysler,
Dodge, Jeep
ER/IF: 12-Volt: 160 Amp;
Remanufactured;
Lester 11240;
PIC 290-5137, -A, -C;

Premium Alternator
 6-Groove Pulley 57.5mm
 Clock Position 2
USED ON:
 2007-09 Chrysler Aspen w/4.7L
 2007-09 Dodge Durango w/3.7L, 4.7L
 2007-09 Dodge Nitro w/3.7L
 2009-13 Dodge RAM Pickup w/3.7L, 4.7L
 2007-10 Jeep Commander w/3.7L, 4.7L
 2007-10 Jeep Grand Cherokee w/3.7L, 4.7L
 2007-09 Jeep Liberty w/3.7L

REPLACES:
DENSO
 421000-0470, -500, -711;
CHRYSLER
 56029914AD, -AF, -AL;



VND0417
For Chrysler, Dodge
ER/IF: 12-Volt: 160 Amp;
Remanufactured;
Lester 11298;
PIC 290-5139C, -D;

Premium Alternator
 7-Groove Pulley 59mm OD
 Clock Position 10
USED ON:
 2007-08 Chrysler Aspen w/5.7L
 2007-08 Dodge Durango w/5.7L
 2007-08 Dodge RAM Pickup w/5.7L

REPLACES:
DENSO
 421000-0410, -580;
CHRYSLER
 56028697AE, -AH;



VND0420
For Chevrolet, Pontiac
IR/IF: 12-Volt: 155 Amp;
Remanufactured;
Lester 11156, 11476;
PIC 290-5219, -A, -598;

Premium Alternator
 6-Groove Pulley 57mm OD
 Clock Position 9
USED ON:
 2007-09 Chevrolet Equinox w/3.4L
 2007-09 Pontiac Torrent w/3.4L
 2008-09 Saturn VUE w/3.5L

Small L-F Plug

REPLACES:
DENSO
 104210-2160, -5070, -5420;
GENERAL MOTORS
 15826299, 25862643, 96673482;



VND0457
For Ford Super-Duty
IR/IF: 12-Volt: 125 Amp;
Remanufactured;
Lester 11291;
PIC 290-5294;

Premium Alternator
 8-Groove Pulley 69mm OD
 Clock Position 2
USED ON:
 2008-10 Ford Super-Duty Trucks w/6.4L Dsl Engine

Plug LI-RC-BVS

REPLACES:
DENSO
 104210-5430, -1, -2, -3;
FORD
 7C3T-10300-FB, 7C3Z-10346-A;
MOTORCRAFT
 GL-919;



VND0469
For Pontiac,
Scion, Toyota
IR/IF: 12-Volt: 110 Amp;
Remanufactured;
Lester 11385;
PIC 290-5014, -5;

Premium Alternator
 6-Groove Decoupler Pulley 55mm OD
 Clock Position 9
 Plug S-IG-L-M
 Replaces 100A and 110A Units
USED ON:
 2009 Pontiac Vibe w/1.8L 2009-10 Toyota Corolla w/1.8L
 2008-14 Scion xD w/1.8L 2009-10 Toyota Matrix w/1.8L

REPLACES:
DENSO 104210-2800, -1, -2,
 -5480, -81, -82, -90, -91;
GENERAL MOTORS 88975507;
TOYOTA 27060-0T040, -1,
 -37040, -41, -80, -81;

AUTO



VND0473
For Dodge Light Trucks,
Jeep, Mitsubishi
ER/IF: 12-Volt; 136 Amp;
Remanufactured;

Lester 11276;
PIC 290-5134B, -C, -D;

Premium Alternator
6-Groove Pulley 65mm OD
Clock Position 2
Replaces 100A and 110A Units

USED ON:
2008-11 Dodge Dakota w/3.7L, 4.7L
2007-09 Dodge Durango w/3.7L, 4.7L
2007-08 Dodge RAM Pickup w/3.7L, 4.7L
2007 Jeep Liberty w/3.7L
2008-09 Mitsubishi Raider Pickup w/3.7L

REPLACES:
DENSO
421000-0430, -590, -591;
CHRYSLER
4801251AD, 56029700AB, -AD;



VND0475
For Chrysler
ER/IF: 12-Volt; 136 Amp;
Remanufactured;

Lester 11244;
PIC 290-5143A;

Premium Alternator
4-Groove Pulley 60mm OD
Clock Position 12

USED ON:
2006-09 Chrysler PT Cruiser w/2.4L Turbo

REPLACES:
DENSO
421000-0370, -1;
CHRYSLER
05034702AA, 5034702AA;



VND0476
For Chrysler, Dodge
ER/IF: 12-Volt; 160 Amp;
Remanufactured;

Lester 11383;
PIC 290-5176A, -B;

Premium Alternator
6-Groove Pulley 52.5mm OD
Clock Position 2

USED ON:
2008-14 Chrysler 300 w/2.7, 3.5, 5.7, 6.1L
2008-10 Dodge Challenger w/3.5, 5.7, 6.1L
2008-10 Dodge Charger w/2.7, 3.5, 5.7, 6.1L
2008-10 Dodge Magnum w/2.7, 3.5, 5.7, 6.1L

REPLACES:
DENSO
421000-0620, -1;
CHRYSLER
4896805AD, -AE;



VND0480
For Jeep
ER/IF: 12-Volt; 150 Amp;
Remanufactured;

Lester 11241;
PIC 290-5202;

Premium Alternator
6-Groove Pulley 54mm OD
Clock Position 9

USED ON:
2007-08 Jeep Commander w/5.7L
2007-08 Jeep Grand Cherokee w/5.7L
2007-09 Jeep Grand Cherokee w/6.1L

REPLACES:
DENSO
421000-0550, -2;
CHRYSLER
56044380A1;



VND0483
For Honda
IR/IF: 12-Volt; 130 Amp;
Remanufactured;

Lester 11392;
PIC 290-5220A;

Premium Alternator
6-Groove Pulley 66mm OD
Clock Position 12
C-FR-IG-L Square Plug

USED ON:
2008-12 Honda Accord w/3.5L
2010 Honda Crosstour w/3.5L

REPLACES:
DENSO
104210-5910;
HONDA
31100-R70-A01, CSF91;

AUTO



VND0484
For Acura, Honda
IR/IF: 12-Volt: 130 Amp;
Remanufactured;
Lester 11391;
PIC 290-5222B;

Premium Alternator
 6-Groove Pulley 65mm OD
 Clock Position 11
 C-FR-IG-L Square Plug

USED ON:
 Acura Honda
 2010-13 MDX w/3.7L 2008-10 Odyssey w/3.5L
 2009-12 RL w/3.7L 2009-11 Pilot w/3.5L
 2009-14 TL w/3.5L, 3.7L 2009-11 Ridgeline w/3.5L
 2010-14 TSX w/3.5L
 2010-13 ZDX w/3.7L

REPLACES:
DENSO
 104210-5920;
HONDA
 06311-RGW-505,
 31100-RGW-A01, CSF92;



VND0485
For Acura
IR/IF: 12-Volt: 110 Amp;
Remanufactured;
Lester 11154;
PIC 290-5223;

Premium Alternator
 7-Groove Pulley 65mm OD C-FR-IG-L Square Plug

USED ON:
 2007-12 Acura RDX w/2.3L Turbo

REPLACES:
DENSO
 104210-5160;
ACURA
 31100-RWC-A01, CSF16;



VND0488
For Dodge Light Trucks
ER/IF: 12-Volt: 145 Amp;
Remanufactured;
Lester 11378, 11583;
PIC 290-5232, -500;

Premium Alternator
 8-Groove Clutch Pulley 59mm OD
 Clock Position 10

USED ON:
 2007-13 Dodge RAM Pickup w/6.7L Cummins Dsl

REPLACES:
DENSO
 421000-0510, -1, -2, -3;
CHRYSLER
 04801311AD,
 4801311AD, -AE;

DC MOTORS



LTM0003
For Tarp Motor
Applications
Tarp Motor: 12-Volt;

60:1 Gear Ratio Complete Assy.
USED ON:
 Tarp Motor Applications

REPLACES:
 N/A

MARINE



TRM8002
Pump
For Tilt / Trim Motors

USED ON TILT / TRIM MOTORS:
 AEP TRM0027

REPLACES:
 N/A

OUTDOOR POWER EQUIPMENT



AVAO167
For John Deere
IR/IF; 12-Volt; 75 Amp;

1-V Pulley 58mm OD
Clock Position 11
USED ON:
John Deere Tractors w/Yanmar Dsl Engines

REPLACES:
JOHN DEERE
LVA18613, -B;
VALEO
2619464;



SPL6045
Solenoid Remote
36-Volt; 4-Terminal;
For White Rodgers

Silver Contacts
5/16-18 Inch Threaded Motor & Battery Studs
10-32 Inch Threaded Studs
USED ON:
1997-On Club Car DS Series (Electric Models)

REPLACES:
WHITE RODGERS
120-20;
CLUB CAR
1120, 1019759-01;

POWERSPORTS



AHD6017-C
Voltage
Regulator / Rectifier
12-Volt;
For Harley Davidson M/C

Shunt Type Chrome Finish
For Black Finish, Use AHD6017
USED ON:
2001-On Harley Davidson Softail (Exc. FXSTD)

REPLACES:
HARLEY-DAVIDSON
74540-01, 74610-01;



SCH0107
For Polaris
Snowmobiles
PMDD; 12-Volt;
CW; 10-Tooth;

Drive Not Included
USED ON:
2014 Bearcat 570, -XT w/565cc
2015 Bearcat 2000, -XT, -XTE w/565cc
2014 F570 w/565cc
2015-16 Lynx 2000, -LT w/565cc
2014 T570 w/565cc

REPLACES:
ARCTCO
0745-392;



SMU0142
For Suzuki M/C
PMDD; 12-Volt;
CCW; 9-Splines;
Lester 18777, 18778;
PIC 190-6169, -A;

14.5mm OD Splines;
USED ON:
1982-85 GS300L w/300cc 1980-88 GS450L w/448cc
1980-83 GS450E w/448cc 1981-82 GS450T w/448cc
1982-83 GS450G w/448cc 1981-83 GS450TX w/450cc
1983-85 GS450GA w/448cc And Many More.

REPLACES:
DENSO
028000-6500, -1, -9550,
-1, 128000-1650, -3580;
SUZUKI
31100-30B00-H17,
-32C00-H17, -43400, -1,
-44110, -1;



SMU6166
Starter Relay
12-Volt;
For Honda ATV

Cord OAL 280mm 1 Male Bullet
1 Female Bullet (w/Sheathing)
Wires on Opposite Side From Most Others
USED ON:
2008 TRX400EX SportTrax 400EX w/397cc
2009-14 TRX400X w/397cc

REPLACES:
HONDA
35850-HN1-A70;



SMU6167
Starter Relay
12-Volt
For Honda ATV, UTV

Relay Only - Will Need to Re-Use Rubber Mounting
Cord Length (Including Plug) 125mm
USED ON:
2008-09 Honda TRX700XX w/686cc ATV
2015-16 Honda Pioneer 500 w/475cc UTV

REPLACES:
HONDA
35850-HP6-A01;

POWERSPORTS



SMU6168
Starter Relay
12-Volt
For Honda M/C

Elongated Mounting Holes

USED ON:
2003-08 Honda VTX1800

REPLACES:
HONDA
35850-ZJ1-811;



SND6076
Starter Relay
12-Volt;
For Yamaha M/C

Mounting Studs 6mm x 1.0 x 40mm (Installed)
Plunger Depth at Rest 20mm

USED ON:
1986-87 Virago XV700 w/696cc
1987-97 Virago XV750 w/749cc
1984-85 XV1000 w/981cc
1986-99 Virago XV1100 w/1063cc
1996-98 Virago XV1100 SP Special w/1063cc

REPLACES:
HONDA
5A8-86110-50-00;

REFRIGERATION



AVA0168
For Refrigeration
IR/IF; 12-Volt;
105 Amp; CCW;

USED ON:
Refrigeration Applications

REPLACES:
CARRIER TRANSICOLD
30-01114-02;
LEECE NEVILLE
A1742B;

COMPONENTS



AND5011
Pulley, 4-Groove
For Toyota
PIC 7990-9030;

#G 4 L 26.7mm ROT N/A
OD of Pulley 61.7mm ID 15mm Screw N/A
Rib OD 54.5mm

REPLACES:
N/A

USED ON:
Toyota Alternators
Lester 13241, 13326, 13339, 13392, 13411, 13455, 13455, 13456, 13486,
13486, 13496, 13500, 13509, 13509, 13536, 13536, 13670, 13671,
13671, 13679, 13711, 13896, 14449,
14449, 14449, 14472, 22410;

WE KEEP YOU RUNNING

MAIN LOCATION
CALL: (800) 328-5454
FAX: (763) 255-2530
3787 95th Ave. NE
Blaine, MN 55014

WEST COAST
CALL: (800) 457-1728
FAX: (209) 537-2856
821 Oates Court
Modesto, CA 95358

CANADA
CALL: (877) 617-2888
FAX: (416) 645-1972
398 Canarctic Drive
North York, Ontario M3J 2V3