

Phone: (763) 255-2555

(800) 328-5454

FAX: (763) 255-2530



3787 95th Ave. N.E.

Blaine, MN 55014

info@arrowheadep.com

www.arrowheadep.com

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS



ABO6023
VOLTAGE REGULATOR, INTERNAL
12-VOLT; A-CIRCUIT;
w/BRUSHES
PIC # 8020-1166;
USED ON CARRIER, THERMO-KING
LESTER 12223, 12224, 12333, 12334, 12334;
REPL.: **BOSCH**
9-190-067-018;
THERMO-KING
44-9143;
REFERENCE NUMBER
IB392; 35-9115



ADR0401
IR/IF;
12-VOLT; 145 AMP;
LESTER 8495-3;
PIC 240-6211, -A;
Used on Chevrolet Kodiak / GMC Topkick 6.6L, 8.1L 2003-05
REPL.: **DELCO**
10480480, 15087022



AFD0118
FOR 3G SERIES;
12-VOLT; 130 AMP;
2:00 Plug Position;
LESTER 8446; PIC 250-462;
Used on:
2006 Ford Ranger w/4.0L
2006 Mazda B-Series Pickup w/4.0L
REPL.: **FORD**
4L2T-10300-DB, -DD,
4L2Z-10346-DA



ADR0400
IR/IF;
12-VOLT; 105 AMP;
LESTER 8490-3;
PIC 240-6209;
Used on Chevrolet Kodiak / GMC Topkick 6.6L, 8.1L 2003-05
REPL.: **DELCO**
10464484, 15087021



AFD0112
FOR 4G SERIES;
12-VOLT; 130 AMP;
2:00 Plug Position;
LESTER 8403;
PIC 250-418;
Used on:
2005-06 Ford Escape w/3.0L
2005-06 Mazda Tribute w/3.0L
2005-06 Mercury Mariner w/3.0L
REPL.: **FORD**
5L8T-10300-KC,
5L8T-10300-KD,
5L8Z-10346-KA,
6L8T-10300-KA,
6L8Z-10346-KA



AFD0124
FOR 4G SERIES;
12-VOLT; 130 AMP;
3:00 Plug Position;
LESTER 8442; PIC 250-463;
Used on:
2005-07 Ford Five Hundred w/3.0L
2005-07 Ford Freestyle w/3.0L
2005-07 Mercury Montego w/3.0L
REPL.: **FORD**
5F9T-10300-AC, 5F9Z-10346-AA,
6F9T-10300-AA, -AC,
6F9Z-10346-AA

Phone: (763) 255-2555

(800) 328-5454

FAX: (763) 255-2530



3787 95th Ave. N.E.

Blaine, MN 55014

info@arrowheadep.com

www.arrowheadep.com

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS



AHD0137
FOR 4G SERIES;
12-VOLT; 130 AMP;

3:00 Plug Position;
LESTER 8441;
PIC 250-464;
Used on:
2005-06 Ford Models

REPL.: FORD
6F9T-10300-BA



AHD0153
FOR 6G SERIES;
12-VOLT; 105 AMP;

LESTER 8309;
PIC 250-406B;
Used on:
1998 Ford Contour w/2.0L
1999 Mercury Cougar w/2.0L
1998 Mercury Mystique w/2.0L

REPL.: FORD
98BB-10300-CC,
F8RZ-10346-CC



AHA6041
VOLTAGE REGULATOR,
FOR HONDA ATV,

PIC 8099-1320;
80MM L x 90MM W x 28MM H;
HOLE DISTANCE 60MM;
USED ON HONDA:
TRX250, -EX 1997-05
TRX400, -EX 1999-04

REPL.: HONDA
31600-HM8-003, -013



AMT5023
PULLEY, 6-GROOVE

PIC 7903-2281;
OVERRUNNING CLUTCH STYLE;
21MM BELT x 54MM OD x 17MM BORE;
USED ON FORD, MITSUBISHI;
LESTER 11026, 11377;

REPL.: INA
F-552562;
REFERENCE NUMBER
24-83275



AMT5024
PULLEY, 6-GROOVE

PIC 7903-2280;
OVERRUNNING CLUTCH STYLE;
21MM BELT x 60MM OD x 17MM BORE;
USED ON MAZDA;
LESTER 13883;

REPL.: MAZDA
GY02-18-330A,
GY02-18-W37Z;
REFERENCE NUMBER
24-2280



AND0200
ER/IF;
12-VOLT; 130 AMP;

LESTER 13964; PIC 290-5146, -5147;
Used on:
2002-04 Chrysler Concorde w/2.7L
2002-04 Dodge Intrepid w/2.7L

REPL.: DENSO
121000-4510, -80;
CHRYSLER
4606822AA, 4608718AA



AND5027
PULLEY, 6-GROOVE

PIC # 7990-9045;
OVERRUNNING CLUTCH STYLE;
41.1MM LENGTH x 55.7MM OD x 17MM BORE;
USED ON VOLVO;
LESTER 13845;

REPL.: DENSO
021040-0970;
REFERENCE NUMBER
24-82275



AND5028
PULLEY, 6-GROOVE

PIC # 7990-9060;
OVERRUNNING CLUTCH STYLE;
57.2MM OD x 17MM BORE;
USED ON JEEP;
LESTER 13961;

REPL.: CHRYSLER
53013579AA;
INA
F-236151



AYA6015
VOLTAGE REGULATOR,
FOR YAMAHA ATV,

PIC 8099-1510;
80MM L x 90MM W x 28MM H;
HOLE DISTANCE 62MM;
THREE PHASE wO/SENSOR;
USED ON YAMAHA:
YFM125 Grizzly 2004-08
YFM250 Bear 2001-04
YFM250 Big Bear 2007-08
YFM250 Bruin 2005-06
YFM350 Bruin 2004-06
YFM350 Grizzly 2007-08
YFM450 Big Bear 2002-08
YFM450 Wolverine 2006-08

REPL.: YAMAHA
5GT-81960-00-00



AYA6016
VOLTAGE REGULATOR,
FOR YAMAHA ATV,

PIC 8099-1510;
90MM L x 97MM W x 28MM H;
HOLE DISTANCE 67.5MM;
THREE PHASE wO/SENSOR;
USED ON YAMAHA:
YFM450 Rhino 2006-08
YFM660 Grizzly 2002-08
YFM660 Rhino 2004-07
YFM700 Raptor 2006-08

REPL.: YAMAHA
5BN-81960-00-00

Phone: (763) 255-2555

(800) 328-5454

FAX: (763) 255-2530



3787 95th Ave. N.E.

Blaine, MN 55014

info@arrowheadep.com

www.arrowheadep.com

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS



IPO6004
CDI MODULE,
FOR POLARIS ATV,
CAPACITIVE DISCHARGE

IGNITION,
PIC 9900-5194;
USED ON POLARIS:
1997-01 ATV Models (Many)

REPL.: POLARIS
3085639



IYA6029
CDI MODULE,
FOR YAMAHA,
CAPACITIVE DISCHARGE

IGNITION,
PIC 9900-5136;
USED ON YAMAHA:
YFM350 Warrior 1996

REPL.: YAMAHA
3GD-85540-30-00



LMN0008
FOR HALDEX-BARNES AERIAL
& SCISSOR LIFTS,
24-VOLT;

PIC 168-9200;
2-Post; Double Ball Bearings;
4.5" Permanent Magnet Case;
Thru bolts at the 3:00 and 9:00;
The Armature shaft is the Amplex or Chrysler
coupler type with 1/4-20 threaded holes;

REPL.: SCOTT MOTORS
2200856, 2200945,
4BD-02273,
SKYJACK
106576, 220856,
SJ-106576;
REFERENCE NUMBERS
W-2273



SBO0111
PMGR; 12-VOLT; CW; 10-TOOTH

LESTER 16595; PIC 120-177A, -B, -C, -6101;
Used on Bobcat, Clark
This Unit is Designed to Replace the Starters
Listed Below:

REPL.: BOSCH
0-001-211-206, -228,
0-001-211-989, -990,
0-001-311-038, -048;
FORD
71BB-11000-BA,
74EB-11000-AA,
76BB-11000-AA,
D1RY-11002-A,
D4RY-11002-A,
R76BB-11000-AA



SBO0182
PMGR; 12-VOLT; CCW; 10-TOOTH

LESTER 17919; PIC 120-435;
Used on:
2002-06 Audi TT Coupe w/1.8L
2002-04 Volkswagen Beetle w/1.8L

REPL.: BOSCH
0-001-121-022, -3;
VOLKSWAGEN
02M-911-023



SFD9021
HARNES LEAD,

FOR FORD PMGR SERIES;
THIS IS USED WHEN REPLACING A SPADE-STYLE
IGNITION TERMINAL STARTER WITH A STUD-STYLE



SMT0228
PMGR; 12-VOLT; CW; 11-TOOTH

LESTER 17908; PIC 103-437;
Used on:
2003-08 Mazda 6 w/2.3L

REPL.: MITSUBISHI
MOT87781;
FORD
3M81-11002-BB;
MAZDA
L321-18-400, -A



SMT0309
PLGR; 24-VOLT; CW; 12-TOOTH

LESTER 19538;
PIC 103-5130;
Used on:
1998-06 Volvo Trucks & Buses

REPL.: MITSUBISHI
M9T61171;
VOLVO
20430564,
85000087



SND0406
FOR KUBOTA,
OSGR; 12-VOLT; CW; 9-TOOTH

LESTER 18004;
PIC 190-425;
Used on Gehl, Kubota, Thomas

REPL.: DENSO
228000-4570, -1,
228000-4572,
228000-4750, -2;
KUBOTA
15425-63014,
15425-63016,
16652-63013

Phone: (763) 255-2555

(800) 328-5454

FAX: (763) 255-2530



3787 95th Ave. N.E.

Blaine, MN 55014

info@arrowheadep.com

www.arrowheadep.com

The information herein is based upon data which we believe to be correct and believe to have been obtained from reliable sources, but no representation is made herein, nor should any be implied, regarding the accuracy of any such information and we assume no liability for any errors or omissions in any such information. Any original equipment manufacturers or other manufacturers or distributors, whose names, numbers, pictures, symbols, products and/or descriptions are, or may be, listed or shown herein are used for reference purposes only and there is no representation made or intended, nor should any be implied, that any item reference herein is the product of, or was manufactured and/or distributed, by, the referenced manufacturer or distributor, as the case may be.
This brochure is intended for reference purposes only. For pricing or terms and conditions, please refer to your price sheet.

10/09

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS



SND0546
OSGR; 12-VOLT; CW; 9-TOOTH

LESTER 17885;
PIC 190-367B;
Used on:
2003-06 Chrysler Sebring w/2.4L
2003-06 Dodge Stratus w/2.4L

REPL.: DENSO
428000-1511,
428000-1512;
CHRYSLER
4609703AF,
4609703AG



SND5071
DRIVE, 8-TOOTH; CW;
6-SPLINE

PIC 6190-2996;
Used on SKI-DOO SNOWMOBILES
LESTER 18874, 18875, 18875, 18875, 18876,
18878;

REPL.: BOMBARDIER
410-922-958



TRM0041
FOR VOLVO-PENTA,

LESTER 10813;
PIC 107-113;
3-Wire;
New Motor and Reservoir

REPL.: PRESTOLITE
EVH4002;
VOLVO
852928



TRM0069
FOR YAMAHA,

LESTER 10855;
PIC 107-155;
2-Wire;
Used on:
Yamaha 115HP 1997-On, 115HP 4-Stroke
2000-On, 130HP 1997-00, 150-200HP 1997-
On, 225HP 1998-On

REPL.: YAMAHA
64E-43880-00-00,
64E-43880-01-00



SND0588
OSGR; 12-VOLT; CW; 10-TOOTH

LESTER 19855;
PIC 190-6320;
Used on New Holland Skid Steers

REPL.: DENSO
428000-3140;
NEW HOLLAND
87040161



SPR0011
FOR BOBCAT,
PLGR; 12-VOLT; CW; 10-TOOTH

LESTER 18485;
PIC 108-302;
Used on Bobcat Skid Steer

REPL.: VALEO
TM000A29001;
BOBCAT
6676958, 6685191



TRM0060
FOR YAMAHA,

LESTER 10833;
PIC 107-133;
2-WIRE (RING TERMINAL ENDS);
3-BOLT MOUNT;
FOR LONGER SHAFT, SEE TRM0071;
Used on 1995-03 Yamaha 40-100HP

REPL.: YAMAHA
62X-43880-00,
62X-43880-01,
62X-43880-09



TRM0077
FOR VOLVO-PENTA,

LESTER 10813A;
PIC 107-113A;
3-Wire
New Motor, Reservoir, and Pump;
This is Designed to Look Like the Original;
For the Aftermarket Design, See TRM0049;

REPL.: PRESTOLITE
EVH4002;
VOLVO
852928