

Phone: (763) 255-2555

(800) 328-5454

FAX: (763) 255-2530



3787 95th Ave. N.E.

Blaine, MN 55014

info@arrowheadep.com

www.arrowheadep.com

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS



ADR5074

PULLEY, 6-GROOVE

PIC # 7940-1283;

FOR AD SERIES ALTERNATORS;

21MM BELT X 57MM DIA. X 17MM BORE;

OVERRUNNING CLUTCH;

LESTER 8241, 8293, 8299, 8491-3;

REPL.: **DELCO**

10484670;

REFERENCE NUMBER

24-1283



ADR6183

VOLTAGE REGULATOR, INTERNAL 12-VOLT;

PIC 8040-6306;

FOR D44G SERIES;

"F-L" TERMINALS; RVC TECHNOLOGY;

LESTER 8301, 8302;

REPL.: **DELCO**

10517755;

REFERENCE NUMBER

D3587



AMT0155

IR/IF;

12-VOLT; 80 AMP;

LESTER 13948; PIC 203-308;

Used on:

2001-02 Kia Rio w/1.5L

2003-05 Kia Rio w/1.6L

REPL.: **MANDO**

AB180140;

KIA

OK30D-18-300,

RK30D-18-300U



AND0253

FOR MERCURY MARINE, 12-VOLT; 60 AMP;

LESTER 12347; PIC 290-476;

Used on Mercury Marine

REPL.: **DENSO**

101211-3460;

MERCURY MARINE

834832, 834832T2



ASU4001

STATOR COIL, FOR SUZUKI M/C,

PIC 7299-2201;

USED ON SUZUKI:

GS250 T 1980-81

GS300L 1982-85

GS400X 1977-78

GS425E 1979

GS425L 1979

GS450ET 1980-82

GS450EX 1980-82

GS450EZ 1980-82

GS450L 1980-88

GS450ST 1980-82

GS450SX 1980-82

GS450T 1981-82

GS450TX 1981-83

GS550E 1977-79

GS550L 1979

GS750B 1977-79

GS750C 1977-79

GS750EC 1977-79

GS750EN 1977-79

GS750N 1977-79

REPL.: **SUZUKI**

31401-45020, -1,

31401-45030



SAB0153

FOR GENERAC, 12-VOLT; CW; 9-TOOTH

LESTER 5787; PIC 106-229;

Used on Generator Sets w/Fiat or

Mitsubishi Engines

REPL.: **GENERAC**

020692

Phone: (763) 255-2555

(800) 328-5454

FAX: (763) 255-2530



3787 95th Ave. N.E.

Blaine, MN 55014

info@arrowheadep.com

www.arrowheadep.com

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS



SAB0162
FOR MEYER,
SNOW PLOW MOTOR,
12-VOLT; CCW;
WITH 3/16" SLOT;
GROUND POST ON CE COVER;

LESTER 5235;

PIC 106-027T;

This is the same as the SAB0001 with the addition of a ground stud on the CE cover

REPL.: **REFERENCE NUMBERS**
W-8032B



SDR0199
FOR 10MT SERIES,
DD; 12-VOLT; CW; 9-TOOTH

LESTER 3631;

PIC 140-105;

Used on Many GM Applications

REPL.: **DELCO**
1107340, 1107352, 1107367,
1107385, 1108320, 1108326,
1108327, AND MANY MORE



SDR0328
FOR 39MT SERIES,
PLGR; 24-VOLT; CW; 12-TOOTH

LESTER 6826;

PIC 141-715;

Used on Cummins Engines

REPL.: **DELCO**
8200027, 8200044,
10461759, 19011512



SBO0028
PMGR; 12-VOLT; CW; 9-TOOTH

LESTER 17039;

PIC 120-317;

Used on:

1985-93 Mercedes 190E w/2.3L

REPL.: **BOSCH**
0-001-108-003, -039;
MERCEDES BENZ
003-151-28-01



SDR0275
FOR 38MT SERIES,
OSGR; 12-VOLT; CW; 10-TOOTH

LESTER 6807;

PIC 141-470;

Used on Heavy-Duty Trucks

REPL.: **DELCO**
8200076, 8300021, 10461768,
19026027



SFD0061
FOR FORD 4.5" MARINE,
12-VOLT; CCW; 9-TOOTH

LESTER 3138, 3144;

PIC 150-0132, -54;

D.E. HOUSING PROTRUDES 2" INTO THE FLYWHEEL;

Used on Crusader, and other marine applications equipped with Ford engines

Phone: (763) 255-2555

(800) 328-5454

FAX: (763) 255-2530



3787 95th Ave. N.E.

Blaine, MN 55014

info@arrowheadep.com

www.arrowheadep.com

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS



SFD0063
FOR FORD 4.5" MARINE,
12-VOLT; CCW; 9-TOOTH

LESTER 3140, 3141;
PIC 150-0149, -52;
D.E. HOUSING HAS TOP MOUNTING HOLE THREADED
Used on Mercruiser and Cobra equipped with Ford engines



SH10084
FOR YANMAR,
DD; 12-VOLT; CW; 9-TOOTH

LESTER 16191;
PIC 104-110;
Used on Yanmar Marine

REPL.: HITACHI
S114-194;
YANMAR
104211-77010, -1



SMT0059
PLGR; 12-VOLT; CW; 12-TOOTH

LESTER 17577; PIC 103-338;
Used on Non-Turbo Models:
1994 Ford Trucks w/7.3L Diesel

REPL.: MITSUBISHI
M8T50171;
FORD
F4PU11000AA, -AC,
F4TZ-11002-B



SMT0259
PMGR; 12-VOLT; CW; 10-TOOTH

LESTER 17913; PIC 103-433;
Used on:
2004 Pontiac GTO w/5.7L
2005-06 Pontiac GTO w/6.0L

REPL.: MITSUBISHI
M0T85582;
GENERAL MOTORS
92169668



SMT0311
FOR HONDA MARINE,
PMGR; 12-VOLT; CW; 13-TOOTH

LESTER 19602, 19603; PIC 103-5160, -5226;
Used on Honda 75-130HP Outboard Engines

REPL.: MITSUBISHI
M0T60381, M0T65081;
HONDA
31200-ZW1-004, 31200-ZW1A-0040,
31200-ZW5-003, 31200-ZW5-0030,
31200-ZW5A-0032



SMU0032
FOR HONDA ATV,
12-VOLT; CW;

LESTER 18338; PIC 191-120;
Used on:

1990-89 FL400RK PILOT
REPL.: HONDA
31200-HE0-003;
MITSUBA
SM-13245

397cc

Phone: (763) 255-2555

(800) 328-5454

FAX: (763) 255-2530



3787 95th Ave. N.E.

Blaine, MN 55014

info@arrowheadep.com

www.arrowheadep.com

The information herein is based upon data which we believe to be correct and believe to have been obtained from reliable sources, but no representation is made herein, nor should any be implied, regarding the accuracy of any such information and we assume no liability for any errors or omissions in any such information. Any original equipment manufacturers or other manufacturers or distributors, whose names, numbers, pictures, symbols, products and/or descriptions are, or may be, listed or shown herein are used for reference purposes only and there is no representation made or intended, nor should any be implied, that any item reference herein is the product of, or was manufactured and/or distributed, by, the referenced manufacturer or distributor, as the case may be. This brochure is intended for reference purposes only. For pricing or terms and conditions, please refer to your price sheet.

6/09

NEW PRODUCTS

NEW REPLACEMENT ALTERNATORS, STARTERS, AND COMPONENTS



SMU0045 FOR HONDA ATC, ATV 12-VOLT; CW;

LESTER 18603;
PIC 191-307;

Used on:

1983-82	ATC200E BIG RED	192cc
1984	ATC200ES BIG RED	192cc
1985-84	ATC200M	192cc
1984	TRX200 FOURTRAX	199cc

REPL.: HONDA
31200-958-681



SND0532 FOR SUZUKI M/C, 12-VOLT;

LESTER 18798;
PIC 190-456;

Used on:

2002-99 GSX1300R HAYABUSA 1298cc

REPL.: DENSO
228000-8480;
SUZUKI
31100-24F00, -1



SND0591 OSGR; 12-VOLT; CW; 10-TOOTH

LESTER 19790;
PIC 190-6028;

This Unit Can Replace Delco #1990406 (42MT).

REPL.: DENSO
228000-9300



STC0015 FOR TECUMSEH, 110-VOLT;

LESTER 5897;
PIC 106-322;

Used on HS, HSSK40-50, OHSK50-60 Engines

REPL.: TECUMSEH
33290, 33290D, 33290E, 33517



STC0020 FOR TECUMSEH, 110-VOLT; CCW; 16-TOOTH

LESTER 5899;
PIC 106-324;

Used on TVM125-140, H, HSK50-70, HSK635 Engines

REPL.: TECUMSEH
33328



TRM0063 FOR SUZUKI,

LESTER 10846; PIC 107-146;
2-WIRE;

REPL.: SUZUKI
38100-87D10-OED,
38100-87E20-OED,
38100-92E00-OED