



NEW PRODUCTS

MAIN LOCATION 800.328.5454 | EAST COAST 855.214.0712 | WEST COAST 800.457.1728 | CANADA 877.617.2888

AG / INDUSTRIAL



AMT0266
For Mitsubishi
IR/IF; 12-Volt;
50 Amp;
Lester 12561;
PIC 203-5071;

USED ON YANMAR ENGINES:
1994-On Mitsubishi S4S, S6S Engines

REPLACES:
MITSUBISHI
A7TA0483, -A;
MITSUBISHI INDUSTRIAL
32A68-00400;



AND0575
For Iseki
IR/IF; 12-Volt;
60 Amp;
Lester 12650;
PIC 290-198E;

1-V Pulley 69mm OD
USED ON:
Iseki Tractors

REPLACES:
DENSO
101211-2040;
ISEKI
6281-200-015-0;



SB00113
For Fiat, Volvo
DD; 24-Volt;
CW; 11-Tooth;
Lester 18253;
PIC 120-6010, -A, -B,
-C, -D;

USED ON:
AIFO
1980-83 M32 S w/5.4L Dsl
1980-83 M32 SD w/4.5L Dsl
1980-83 M42 S w/8.1L Dsl

1980-83 M52 S w/6.7L Dsl
1980-83 MZ Models w/8.1L Dsl
Volvo
1966-80 B50 w/9.6L Dsl
1992-96 B10B w/10.0L Dsl

1994-06 B10L w/9.6L Dsl
1975-06 B10M w/9.6L Dsl
1993-06 B10R w/9.6L Dsl
1984-87 C10M w/9.6L Dsl
And Many More

REPLACES:
BOSCH
0-001-402-040, -402-053,
-410-044, -411-016, -414-008, -415-016,
-416-009, -416-021, -417-002
FIAT
61227993;

KHD
116-1280, 116-1563;
LIEBHERR
600-07-33;
MAN
51262017034, -7048, -7100,
-9034;

MERCEDES BENZ
001-151-29-01;
RENAULT
5000270909;
VOLVO
240504, 465929, 5001683,
4778060-6;



SB00148
For Volvo, Volvo Penta
DD; 24-Volt;
CW; 9-Tooth;
Lester 19758;
PIC 120-6077, -A;

USED ON:
1981-82 4400 Loader
1979-82 4500 Loader
1982 TD60B, TD60D

REPLACES:
BOSCH
0-001-414-022, 0-001-416-026;
VOLVO
4774617, 4881097;

AG / INDUSTRIAL



SB00198

For Deutz Engines,
Others

DD: 12-Volt;
CW: 9-Tooth;

Lester 17105, 17159;
PIC 120-517, -A, -B, 120-525, -A;

USED ON:

Atlas, Deutz, Fuchs, Others

REPLACES:

BOSCH 0-001-354-100, -362-012,
-362-041, -366-001;
AGCO 1164414, 1172683,
01164414-3, 01172683-3;
DEUTZ 1161386;
KHD 116-2510, -1386, -4414, 117-2683;



SB00344

For Mercedes Benz
Engines, Others

DD: 12-Volt;
CW: 9-Tooth;

PIC 900-301;

USED ON:

Case, Deutz, Mercedes Benz

REPLACES:

BOSCH
9-000-083-014, -027, -029, -053;
MERCEDES BENZ
002-151-17-01, 343-151-70-01,
344-151-70-01;



SDR0072

For 50MT Series

DD: 24-Volt;
CW: 11-Tooth;

Lester 4897;
PIC 142-192;

5/8 Inch Mounting Hole

USED ON:

Freightliner, Kenworth, Peterbilt, Others

REPLACES:

DELCO 1109635, -794, -832, -989,
1990241, 10478853;
CATERPILLAR 3T8959, 9L2200,
9L5417;
CUMMINS 3603866RX;
INTL HARVESTER 793785C91;



SDR0354

For 41MT Series

DD: 12-Volt;
CW: 12-Tooth;

Lester 6632;
PIC 141-370;

.41 Inch Mounting Holes

Has Field Case Ground Stud

USED ON:

John Deere Ag/Ind Equipment

REPLACES:

DELCO
10479098;



SND0470

For Onan

DD: 12-Volt;
CCW: 9-Tooth;

Lester 19611;
PIC 190-494;

USED ON:

Onan Engines

REPLACES:

DENSO
228000-0120, -1;
ONAN
191-1906;



SND0780

For Cummins Engines

OSGR: 24-Volt;
CW: 10-Tooth;

Lester 19097;
PIC 190-6048A;

Ground Stud on D/E Frame Points Outward

USED ON:

Cummins Engines

REPLACES:

DENSO
428000-1340;
CUMMINS
3957597;

AG / INDUSTRIAL



SNK1000
C/E Frame
For 28MT Series
PIC 5785-8801;

USED ON:
Lester 6570, 6571, 6572, 6573, 6574, 6575, 6576, 6577, 6578, 6579, 6580, 6581, 6582, 6583, 6584, 6585, 6586, 6587, 6588, 6589, 6590, 6591, 6592, 6593, 6594, 6595, 6596, 6597, 6598, 6599, 6600, 6601, 6602, 6604, 6610, 6611, 6860, 6901, 6902, 6903;

REPLACES:
DELCO
10457036;



SNK6026
Solenoid
Control Relay
24-Volt;
For Nikko

3-Wire Green Plug
USED ON:
Nikko Starters For Ag/Industrial Applications

REPLACES:
NIKKO
0-25000-6890, -6900, -6901, -6902, -6903, -6910, -6911, -6912, -6913, -6960, -6961, -6962, -6963, -8370, -8371, -8810;



SNK9103
Parts Kit
For Delco
PIC 6940-791;

Repair Kit for Delco 12V 28MT Series OSGR Starters
USED ON:
Lester 6468, 6469, 6570, 6571, 6572, 6573, 6575, 6576, 6577, 6578, 6579, 6580, 6581, 6583, 6584, 6585, 6586, 6587, 6588, 6589, 6590, 6593, 6595, 6599, 6600, 6601, 6602, 6603, 6604, 6610, 6611, 6903;

AUTO



AB00349
For Volvo
IR/IF: 12-Volt;
180 Amp
Lester 11223;
PIC 220-5478, -A;

6-Groove Pulley 52mm OD
USED ON:
2007-10 Volvo S80 w/4.4L
2005-11 Volvo XC90 w/4.4L

REPLACES:
BOSCH
0-121-715-002, -032, -102;
VOLVO
30667018, -524, -525, -896, 30782032, -2-0, 30795210, 36000791, -1-0, 36002176, -6-0, 8603388, -605, -898, -898-0;



AB00391
For BMW
IR/IF: 12-Volt;
180 Amp;
Lester 11301;
PIC 220-5481;

6-Groove Clutch Pulley 49mm RIB OD
USED ON:
2008-13 BMW 128 Series w/3.0L 2007-10 BMW X3 w/3.0L
2007-09 BMW 323 Series w/2.5L 2007-10 BMW X5 w/3.0L
2007-13 BMW 328 Series w/3.0L
2008-09 BMW 528 Series w/3.0L

REPLACES:
BOSCH
0-121-715-012, -112;
BMW
12-31-7-550-968, -551-256, -555-926



AB00394
For BMW
IR/IF: 12-Volt;
180 Amp;
Lester 11302;
PIC 220-5484;

7-Groove Clutch Pulley
USED ON:
2008-10 BMW 135 Series w/3.0L
2007-13 BMW 335 Series w/3.0L
2008-10 BMW 535 Series w/3.0L
2011-12 BMW M1 w/3.0L

REPLACES:
BOSCH
0-121-715-016;
BMW
12-31-7-557-789, -8-219, -8-220;



ADRO240-220
For CS130D Series
IR/IF: 12-Volt;
220 Amp;

6-Groove Pulley 49mm OD High Amp Version of ADRO240
This Can be Used in the Same Applications as the ADRO240 Where Higher Amperage is Desired. High Amp Units Such as This Should be Professionally Installed as Part of a Total Charging System Analysis and Upgrade.
USED ON:
GM Applications

AUTO



ADR0290-220
For AD244 Series
IR/IF: 12-Volt;
220 Amp;
Lester 8292-200;
PIC 240-6223H;

6-Groove Pulley 49mm OD High Amp Version of ADR0290
This Can be Used in the Same Applications as the ADR0290 Where Higher Amperage is Desired. High Amp Units Such as This Should be Professionally Installed as Part of a Total Charging System Analysis and Upgrade.

USED ON:
Buick, Chevrolet/GMC, Isuzu Light Trucks



ADR0368-250
For DR44G Series
IR/IF: 12-Volt;
250 Amp;

6-Groove Pulley 49mm OD High Amp Version of ADR0368
This Can be Used in the Same Applications as the ADR0368 Where Higher Amperage is Desired. High Amp Units Such as This Should be Professionally Installed as Part of a Total Charging System Analysis and Upgrade.

USED ON:
2005-10 Chevrolet/GMC Light Trucks



AFD0039-250
For 3G Series
IR/IF: 12-Volt;
250 Amp;

High Amp Version of AFD0039
This Can be Used in the Same Applications as the AFD0039 Where Higher Amperage is Desired. High Amp Units Such as This Should be Professionally Installed as Part of a Total Charging System Analysis and Upgrade.

USED ON:
Ford Applications



AFD0045-220
For 4G Series
IR/IF: 12-Volt;
220 Amp;

High Amp Version of AFD0045
This Can be Used in the Same Applications as the AFD0045 Where Higher Amperage is Desired. High Amp Units Such as This Should be Professionally Installed as Part of a Total Charging System Analysis and Upgrade.

USED ON:
1996-04 Ford Light Trucks



AFD0075-220
For 6G Series
IR/IF: 12-Volt;
220 Amp;

High Amp Version of AFD0075
This Can be Used in the Same Applications as the AFD0075 Where Higher Amperage is Desired. High Amp Units Such as This Should be Professionally Installed as Part of a Total Charging System Analysis and Upgrade.

USED ON:
2001-04 Ford Mustang w/3.8L



AFD0148
For 6G Series
IR/IF: 12-Volt;
110 Amp;
Lester 8418;
PIC 250-417, -29;

6-Groove Clutch Pulley
USED ON:
2002-04 Ford Focus w/2.0L

REPLACES:
FORD
2MSU-10300-AA, 2M5V-10300-AA,
2M5Z-10346-AB;



SMT0432
For Ford
PMGR: 12-Volt;
CW: 11-Tooth;
Lester 19138;
PIC 103-5178;

USED ON:
2011-16 Ford Fiesta w/1.6L

REPLACES:
MITSUBISHI
MOT33571;
FORD
AE8T-11000-AB, BE8Z-11002-A;

AUTO



SMT0435
For Subaru
PMGR: 12-Volt;
CCW: 9-Tooth;
Lester 19268;
PIC 103-5332;

USED ON:
2014-15 Forester w/2.5L
2012-15 Impreza w/2.0L
2015 Legacy w/2.5L
2015 Outback w/2.5L
2015 WRX w/2.0L
2013-14 XV Crosstrek w/2.0L

REPLACES:
MITSUBISHI
MOT38571, MOT38571ZC;
SUBARU
23300-AA710, 23300-AA71A;



SND0663
For Scion
PMGR: 12-Volt;
CW: 10-Tooth;
Lester 19048;
PIC 190-6375;

USED ON:
2008-14 Scion XD w/1.8L

REPLACES:
DENSO
428000-4940, -4941, -4942;
TOYOTA
28100-37040, -1;

HD TRUCKS



SB00146
For Volvo
Trucks, Buses
DD: 24-Volt;
CW: 11-Tooth;
Lester 18931;
PIC 120-6088A, -AB;

USED ON:
1991-94 B12 w/12.0L Dsl
1977-94 F10 w/9.6L Dsl
1985-01 FL10 w/9.6L Dsl
1999-03 FM10 w/9.6L Dsl
1987-95 FS10 w/9.6L Dsl
1987-94 F12 w/12.0L Dsl
1978-88 N10 w/9.6L Dsl
1988-98 N12 w/12.0L Dsl
1989-01 NL10 w/9.6L Dsl
1989-01 NL12 w/12.0L Dsl

REPLACES:
BOSCH 0-001-416-005, -410-046;
AVF IM326, IM505;
MAN 51262017029, 81262019029;
RENAULT 5010217215;
VOLVO 240340, 465930, 5001680,
7240340;



SDR0402
For 42MT Series
DD: 12-Volt;
CW: 11-Tooth;
Lester 6775;
PIC 142-348;

w/OCP
w/IMS System
USED ON:
1994-02 Volvo ACL42 / ACL64 Series
2001-02 VHD Series
1994-04 VNL Series
1997-03 VNM Series
1990-03 WA/WC/WG/WH/WI/WX Series

REPLACES:
DELCO
10461165, 10461213, 10461268,
10479030, 10479157;



SND0777
For Cummins
OSGR: 12-Volt;
CW: 10-Tooth;

Ground Stud On D/E Frame Points Outwards
USED ON:
Cummins Applications

REPLACES:
DENSO
428000-2860;
CUMMINS
3971603;

OUTDOOR POWER EQUIPMENT



SB07559
Brush Set

23.5mm L x 14mm W x 6mm H x 31mm LL
USED ON:
Bosch Starter-Generator For Golf Carts
Bosch 0-010-350-018

REPLACES:
BOSCH 2-014-320-012, 2-017-014-
102, -3, -4, -5;
MERCEDES BENZ 000-154-02-14;
VOLVO 870840;

POWERSPORTS



AHA6101
Voltage
Regulator / Rectifier
12-Volt;
For Honda M/C

USED ON:
2003-12 XR125L w/125cc

REPLACES:
HONDA
31600-KRH-921, -D01;
SHINDENGEN
SH572LA;



AKM6000
Voltage
Regulator / Rectifier
12-Volt;
For Beta, KTM M/C

USED ON:
2005-15 Beta, Husaberg, KTM Models

REPLACES:
KTM 80011034000;
BETA 2728101000;
SHINDENGEN SH721AA;



APO6020
Voltage
Regulator / Rectifier
12-Volt;
For Polaris ATV

96mm L x 69mm W x 37mm T
(3) Yellow Wires in Plug - 4 Inches Long
(1) Yellow / Red Wire w/Female Butt Connector 5.5 Inches Long
(1) Red B+ Wire in Black Sheathing w/Eyelet - 8.75 Inches Long
(1) Black B- Wire w/Eyelet - 8.75 Inches Long

REPLACES:
POLARIS 4011182;

USED ON:
2006-11 Hawkeye 300 2x4 w/299cc 2008-10 Sportsman 300 w/299cc
2006-08 Hawkeye 300 4x4 w/299cc 2008-10 Sportsman 400 HO 4x4 w/455cc



APO6022
Voltage
Regulator / Rectifier
12-Volt;
For Polaris ATV, UTV

96mm L x 68mm W x 37mm T
Mtg. Holes Center-to-Center 80mm
Plug #1 (3-Yellow Wires) 5 Inches OAL
Plug #2 (1-Red, 1-Black Wire) 5.5 Inches OAL
(1) Yellow w/Red Wire w/Female Bullet 4.5 Inches OAL

REPLACES:
POLARIS
4012192;

USED ON:
2009-14 Polaris ATV, UTV Many Models



APO6028
Voltage
Regulator / Rectifier
12-Volt;
For Polaris ATV, UTV

111mm L x 111mm W x 52.5mm H
Plug #1 - (3) Yellow Wires, 7.25 Inches OAL
Plug #2 - (2) Red Wires, (2) Black Wires, 5 Inches OAL
(1) Yellow w/Red Wire, Female Bullet Connector, 7 Inches OAL

REPLACES:
POLARIS
4011569, 4011925, 4012384;

USED ON:
2008-09 Ranger 4X4 500 EFI w/499cc UTV 2008-09 Sportsman 500 X2 EFI w/499cc ATV
2007-09 Ranger 6X6 700 EFI w/683cc UTV 2007-09 Sportsman 800 EFI w/760cc ATV
2008-09 RZR 800 EFI w/760cc UTV And Many More



ASU4025
Stator Coil
For Suzuki M/C

USED ON:
2011-15 Suzuki GSX-R600 w/599cc
2011-15 Suzuki GSX-R750 w/749cc

REPLACES:
SUZUKI
31401-01H20;



ASU6025
Voltage
Regulator / Rectifier
12-Volt;
For Suzuki M/C

USED ON:
1992-95 DR650SE w/650cc
2005-09 VS1400GLP S83 Boulevard Cruiser w/1360cc
1996-04 VS1400GLP Intruder w/1360cc
2005-09 VS800 S50 Boulevard w/805cc
1996-04 VS800GL Intruder w/805cc

REPLACES:
SUZUKI
32800-12E00, 32800-12E01;
SHINDENGEN
SH576A-12;

POWERSPORTS



ASU6028
Voltage
Regulator / Rectifier
12-Volt;
For Suzuki M/C

144mm L x 49mm W x 26mm T
Mounting Holes 128mm Center-to-Center
Plug #1 - 2 Red (B+), 2 Black (B-), 1 Orange (Ignition)
Plug #2 - (3) Yellow Wires (Charging Coil)
USED ON:
1987-95 VS1400GLP Intruder w/1360cc

REPLACES:
SUZUKI
32800-38B00;



SHD5302
Jack Shaft
For Harley Davidson
CW: 9-Tooth;

5-1/2 Inch Length 17.30mm OD on End
USED ON:
1989-93 Harley Davidson Big Twin



SMU0393
For Honda M/C
PMDD; 12-Volt;
CCW: 9-Spline;
Lester 18680;
PIC 191-442;

USED ON:
2003-10 ST1300 w/1261cc
2003-13 ST1300A w/1261cc
2005-16 ST1300PA w/1261cc

REPLACES:
HONDA
31200-MCS-003;



SMU6139
Starter Relay
12-Volt;
For Kawasaki
ATV, M/C

Battery Stud Left Front (Fuse in Rear), 20A Fuse
Relay Easily Removed From Rubber Mount
USED ON:
1993-96 KLX650 w/651cc M/C
1988-02 KLF220 Bayou 220 w/215cc ATV
2003-11 KLF250 Bayou 250 w/228cc ATV

REPLACES:
KAWASAKI
27010-0768, -1243, -1283;



SMU6143
Starter Relay
12-Volt;
For Kawasaki M/C

Battery Stud Left Front, 30A Fuses
New Part Requires Re-Use of Existing Rubber Mount
USED ON:
2009-10 ER650 ER-6N w/649cc
2013-15 EX300 Ninja 300 w/296cc
2013-15 EX300 Ninja 300 ABS w/296cc

REPLACES:
KAWASAKI
27010-0099;
2009-11 EX650 Ninja 650R w/649cc
2011-15 KLE650 Versys w/649cc
2014-15 KLE650 Versys ABS w/649cc



SND0232
For Suzuki M/C
PMDD; 12-Volt;
CCW: 9-Spline;
Lester 18743, 18744,
18781;
PIC 190-6111, -A, 191-466;

USED ON:
1991-93 GSF400 Bandit w/398cc
1996-03 GSF600S Bandit w/599cc
1998-06 GSX600F Katana w/599cc
1998-06 GSX750F Katana w/750cc

REPLACES:
DENSO
128000-6791, 128000-7590,
228000-7050;
SUZUKI
31100-08F00, 31100-10D00, 31100-
32C11;



SSE7505
Brush, 12-Volt;
For Honda
PIC 5491-3011;

14mm L x 15mm W x 7mm H
USED ON:
Honda Powersports and Small Engine Applications

REPLACES:
HONDA
31201-253-004;

COMPONENTS



ADR6198
Voltage Regulator
12-Volt;
(w/Brushes)
For Delco

Set Point: 14.0V
USED ON:
Korean Delco Alternators
Lester 8486;

REPLACES:
REFERENCE NUMBER
D816:



AND6004
Voltage Regulator,
External;
12-Volt;
For Denso

Set Point: 14.3 Volts B-Circuit
Voltage: 12 Volts Negative Ground
Activation: Ignition
USED ON:
1967-74 Toyota, Suzuki
Automotive and Light Truck Applications

REPLACES:
DENSO 026000-1102,
-1105, -1202, -1321, -1341,
-1730, -1740, -1741, -1742,
-1750, -1751, -1871, -2121,
-2271, -2430, -2431, -3250,
-3780, -3810, -3920;
SUZUKI 32500-56010;
TOYOTA 27700-10110,
-10171, -13050, -15020,
-15030, -22010, -22011,
-22012, -31010, -31011,
-33010, -33011, -40020,
-40021, -41040, -51010,
-51011, -51012;



SB03083
Armature, 12-Volt;
For Bosch Starters
PIC 5020-2037;

9-Spline DE Shaft Diam 8mm
Comm Diam 52mm 28-Comm Bars
Core Diam 12.5mm OAL Arm 114mm
USED ON: Spline Type Straight
Bosch 107, 121 Series Starters
Lester 17702, 17730, 17822, 17920, 17922, 17967, 17970, 17975, 19001, 19110, 30898, 31167,
31221, 31244, 32708, 33071, 33115, 33116, 33169, 33206, 33291, 33295, 33302, 33320;

REPLACES:
BOSCH 1-004-011-210, -212;
FIAT 9949609;
TOYOTA 28160-0D130;



SDR1343
Brush Holder,
12-24 Volt;
For Delco Starters
PIC 5540-500;

Includes Negative Brushes
USED ON:
Delco 39MT Starters (2nd Generation)
Lester 6802, 6804, 6805, 6806, 6812, 6813, 6814, 6818,
6819, 6822, 6853;

REPLACES:
REFERENCE NUMBER
69-125;



SND7544
Brush, 12/24-Volt;
For Denso Starters
PIC 5540-500;

21mm L x 25mm W x 8mm H x 43mm LL
Note: w/Insulated Lead
Note: w/Clip
For Brush wo/Clip, Use SND7506
USED ON: 17286, 17302, 17313, 17362, 17362A, 17376, 17380, 17399, 17418,
Denso 2.5kw OSGR Starters 17462, 17548, 17609, 17892, 18138, 18181, 18190, 18483, 18507,
Lester 16494, 16824, 16896, 18548, 18560, 18936, 19553, 19614, 19618, 19748, 19789, 19806,
16897, 16967, 16990, 17198, 19857, 19905, 19924, 19960, 19962, 19963, Others

REPLACES:
DENSO
028099-3560;



SMT7528
Brush, 12-Volt;
For Mitsubishi
Starters

4.3mm T x 11.8mm W x 12.2mm L x 60mm LL
USED ON:
Mitsubishi PMGR Starters
Lester 17873, 17874, 17933, 17937, 17939;

REPLACES:
REFERENCE NUMBER 68-8336;

MAIN LOCATION
CALL: (800) 328-5454
FAX: (763) 255-2530
3787 95th Ave. NE
Blaine, MN 55014

EAST COAST
CALL: (855) 214-0712
FAX: (508) 857-0586
145 Bodwell Street
Avon, MA 02322

WEST COAST
CALL: (800) 457-1728
FAX: (209) 537-2856
821 Oates Court
Modesto, CA 95358

CANADA
CALL: (877) 617-2888
FAX: (416) 645-1972
398 Canarctic Drive
North York, Ontario M3J 2V3

WE KEEP YOU RUNNING