



NEW PRODUCTS

MAIN LOCATION 800.328.5454 | EAST COAST 855.214.0712 | WEST COAST 800.457.1728 | CANADA 877.617.2888

AG / INDUSTRIAL



AB05058
Pulley, 8-Groove;
For John Deere
 PIC 7920-2210;

OD of Pulley 69mm
 Rib OD 62mm
USED ON:
 Lester 12492, 12795, 12880;

REPLACES:
BOSCH
 F-00M-061-024, -0243VT;



AND0432
For Caterpillar
IR/EF; 24-Volt;
50 Amp;
Lester 12060;
 PIC 290-172, -473;

USED ON:
 Caterpillar Industrial Equipment

REPLACES:
DELCO
 100211-0890, 101211-6100;
CATERPILLAR
 100-5045, -7, OR3667, 5S9088,
 6T7223, 7T6173;



SDR0145
For 50MT Series
DD; 24-Volt;
CW; 11-Tooth;
Lester 3902;
 PIC 142-188;

USED ON CATERPILLAR:
 1986-93 3508, 3512, 3516 Industrial Engines
 1986-93 3508, 3512, 3517 Marine Engines w/8cyl 2105ci 34.5L
 Mining Excavators
 2006-On 5130 w/Cat. 3508 2006-On 5130B w/Cat. 3508B
 Off-Road & Mining Trucks
 1986-92 776B w/Cat. 3508 1986-92 777B w/Cat. 3508
 1992-97 776C w/Cat. 3508 1992-00 777C w/Cat. 3508
 Pipelayers
 1983-89 583K w/D-342 Dsl 1983-92 591 w/Cat. 3412
 1983-92 589 w/Cat. 3408 1981-86 594H w/D-353 Dsl
 Track Tractors
 1982-92 D8L w/Cat. 3408 1980-86 D9L w/Cat. 3412
 1986-95 D9N w/Cat. 3408 1986-93 D10N w/Cat. 3412

REPLACES:
DELCO
 1109555, -781, -788, -789, 1109833,
 -834, -9836, 1990233, -234, -291,
 1993753, 10455855, 10461103;
CATERPILLAR
 OR2697, OR4267, 3T2782, -3, -4,
 3T8452, 6T0643, 6V0513, -889,
 -928, 7N6056, 7T9162, 9G6096, -7;
CUMMINS
 3604658RX;



SIA0010
For Case, New Holland
PLGR; 12-Volt;
CW; 10-Tooth;
Lester 19860;
 PIC 182-593;

USED ON:
 2008-On Case Farm Tractors
 2008-On New Holland Crawler Tractors, Farm Tractors

REPLACES:
CASE/ NEW HOLLAND
 82036365, 84208918, 87398251;
LETRIKA 11.131.570, 11.131.921,
 AZE4139, AZE4194, IS 1189;
MAHLE MS24;

AG / INDUSTRIAL



SIA0011
For Case, IHC, JCB, Massey Ferguson, New Holland, Others
PLGR: 12-Volt;
CW: 10-Tooth;
 PIC 120-641;

USED ON:
 Case, Int'l Harvester, JCB, Massey Ferguson, New Holland, Terex, and Many Other Applications

REPLACES:
BOSCH
 0-001-367-040;
LETRIKA
 11.132.159, AZE4244, IS 0631, IS 1378;
MAHLE
 MS49, MS395;



SMT5066
Drive
For Mitsubishi Industrial Engines
CW: 20-Spline;
 PIC 6103-2663;

Gear Splines: 20
 Spline: OD 14.6mm
 OAL: 91.5mm
 Clutch Type: Roller
 # Splines: 5 (Spiral)

Notes:
 19.8mm Shaft OD
 21.20mm Spline Length

REPLACES:
MITSUBISHI
 M191X69871, M191X94271;

USED ON:
 Lester 18974, 30026;

AUTO



AMT0218
For Mazda
ER/IF: 12-Volt;
110 Amp;
Lester 11398;
 PIC 203-5084A;

6-Groove Pulley 49mm OD
 Clock Position 9
 3-Terminal Plug (Blank)-D-P
USED ON:
 2008-10 Mazda 5 w/2.3L

REPLACES:
MITSUBISHI
 A3TJ1091;
MAZDA
 LFB6-18-300;



AMT0277
For Honda
IR/IF: 12-Volt;
110 Amp;
Lester 14489;
 PIC 203-677;

7-Groove Decoupler Pulley 57mm OD
 Clock Position 2
USED ON:
 2013-16 Honda Accord w/2.4L

REPLACES:
MITSUBISHI
 A5TL0581ZC;
HONDA
 31100-5A2-A02, -A02RM, AHGA88;



AMT0278
For Acura, Honda
IR/IF: 12-Volt;
95 Amp;
Lester 11537;
 PIC 203-5347;

6-Groove Pulley 59mm RIB OD
 Clock Position 4
 Single Pin (LIN System)
USED ON:
 2013-15 Acura ILX w/2.0L 2016 Honda HR-V w/1.8L
 2012-2015 Honda Civic w/1.8L

REPLACES:
MITSUBISHI
 A5TJ0191, -1ZC, -1ZE;
HONDA
 31100-R1A-A01, AHGA81;



AND0602
For BMW
IR/IF: 12-Volt;
210 Amp;
Lester 11791;
 PIC 290-6001;

8-Groove Clutch Pulley 49mm OD
 Clock Position 6
USED ON:
 2009-11 BMW 528 Series w/3.0L
 2011-12 BMW X3 w/3.0L

REPLACES:
DENSO
 104210-6250, -1, -4;
BMW
 12-31-7-591-268, -271;

AUTO



AVA0043
For Mercedes Benz
IR/IF: 12-Volt;
120 Amp;
Lester 11123;
PIC 208-549;

6-Groove Pulley 50mm OD 2-Terminal Plug Marked 1-2
USED ON:
 2001-02 Mercedes Benz CLK Class w/3.2L
 2002-03 Mercedes Benz E Class w/3.2L

REPLACES:
VALEO
 439307, -12, 2542320, SG12B024;
MERCEDES BENZ
 011-154-62-02, A011-154-62-02;



SB00124
For Volkswagen
PMGR: 12-Volt;
CCW: 10-Tooth;
Lester 17750;
PIC 108-288, 120-385, -A;

USED ON:
 1995-97 Volkswagen Eurovan w/2.4L Dsl
 1996 Volkswagen Eurovan w/2.5L
 1997-03 Volkswagen Eurovan w/2.8L
 1995-97 Volkswagen Vanagon w/2.4L Dsl

REPLACES:
BOSCH 0-001-124-005, -6,
 0-001-125-001, -02, -11, -31, -32;
LETRIKA IS 1042;
MAHLE MS384;
VALEO D7RS31, VS508;
VOLKSWAGEN
 02B-911-023B, -D, -J, -N;



SDR0378
For PG260 Series
PMGR: 12-Volt;
CW: 8-Tooth;
Lester 6950;
PIC 140-6073;

USED ON:
 2009 Hyundai Genesis w/3.8L
 2008 Kia Sorento w/3.3L
 2007-08 Kia Sorento w/3.8L

REPLACES:
DELCO
 8000173;
HYUNDAI
 36100-3C022, -3;



SDR0380
For PG260 Series
PMGR: 12-Volt;
CW: 9-Tooth;
Lester 6971;
PIC 140-6088;

USED ON:
 2009-14 Cadillac CTS w/6.2L (376) V8
 2016 Chevrolet Silverado 2500 HD, 3500 HD w/6.0L (364) V8
 2016 GMC Sierra 2500 HD, 3500 HD w/6.0L (364) V8

REPLACES:
DELCO
 8000261;
GENERAL MOTORS
 19180527;



SDR0430
For PG260 Series
PMGR: 12-Volt;
CW: 12-Tooth;
Lester 6989;
PIC 140-6016;

USED ON:
 2011-15 Hyundai Azera w/3.3L
 2013-15 Hyundai Santa Fe w/3.3L
 2014 KIA Cadenza w/3.3L
 2015-16 KIA Sedona w/3.3L
 2014-16 KIA Sorento w/3.3L

REPLACES:
DELCO
 8000470;
HYUNDAI
 36100-3C221;



SMT0423
For Ford
PMGR: 12-Volt;
CW: 13-Tooth;
Lester 19260;
PIC 103-907;

USED ON:
 2013-14 Ford F-150 w/3.5L (213) V6, 3.7L (225) V6
 2013-14 Ford Mustang w/3.7L (225) V6
 2015 Ford Transit Van 150 w/3.5L (213) V6, 3.7L (225) V6
 2015 Ford Transit Van 250 w/3.5L (213) V6, 3.7L (225) V6
 2015 Ford Transit Van 350 w/3.5L (213) V6, 3.7L (225) V6

REPLACES:
MITSUBISHI
 MOT39571ZC;
FORD
 CK4T-11000-BA, CK4Z-11002-A;

AUTO



SMT0428
For Mazda
PMGR: 12-Volt;
CW: 13-Tooth;
Lester 19286;
PIC 103-5146;

USED ON:
2012-14 Mazda 2 w/1.5L

REPLACES:
MITSUBISHI
MOT36771;
MAZDA
Z145-18-400;



SMU0495
For Acura
PMGR: 12-Volt;
CW: 11-Tooth;
Lester 17953;
PIC 191-189;

USED ON:
2007-09 Acura RDX w/2.3L

REPLACES:
MITSUBA
SM710-06;
ACURA
31200-RWC-A01, RWC5L;



SND0653
For Lexus, Toyota
PLGR: 12-Volt;
CW: 9-Tooth;
Lester 19045;
PIC 190-6241, -2;

USED ON:
2008-10 Lexus LX570 w/5.7L
2008-10 Toyota Landcruiser w/5.7L
2008-10 Toyota Sequoia w/5.7L
2007-10 Toyota Tundra Pickup w/5.7L

REPLACES:
DENSO
428000-3960, -1;
TOYOTA
28100-0S010, -0S011, -38040,
-38041;



SND0657
For Subaru
PMGR: 12-Volt;
CCW: 9-Tooth;
Lester 19073, 19284;
PIC 190-6249, -6439;

USED ON:
2008-14 Subaru Legacy w/2.5L
2008-09 Subaru Legacy w/3.0L
2015-16 Subaru Legacy w/3.6L
2008-14 Subaru Outback w/2.5L
2008-09 Subaru Outback w/3.0L
2015-16 Subaru Outback w/3.6L

REPLACES:
DENSO
428000-4790, 438000-0540;
SUBARU
23300-AA59A, -B;



SND0782
For Acura, Honda
12-Volt;
CCW: 19-Tooth;
Lester 19182, 19986;
PIC 190-6342, 920-3376;

USED ON:
2010-13 Acura MDX w/3.7L
2013-16 Acura RDX w/3.5L
2010-13 Acura ZDX w/3.7L
2011-13 Honda Odyssey w/3.5L

REPLACES:
DENSO
428000-6780, -9360;
HONDA
31200-R8A-A01, R8A-A01RM,
-RYE-A71, DV4DB, DUDV3;



SND1333
Brush Holder, 12-Volt;
For Land Rover

USED ON:
Denso Starters for Land Rover Applications
Lester 17890;

REPLACES:
DENSO
028510-5830;

HD TRUCKS



SDR0060
For 42MT Series
DD: 12-Volt;
CW: 12-Tooth;
Lester 6516;
PIC 142-264, -A;

Right Hand Mount 5/8 Inch Mounting Holes
Special Open Cut Drive End Housing
USED ON:
1985-97 Caterpillar Industrial and Marine Engines
Medium & Heavy Duty Trucks w/Caterpillar 3306 Engines
1987-00 Ford, Freightliner, Kenworth, Sterling, Volvo,
Western Star, White
1986-94 Peterbilt w/Caterpillar 3306, 3406 Engines
1990-94 Ford B600 / B700 / B800 School Bus w/Caterpillar 3306

REPLACES:
DELCO
1990349, -0372, -3813, -3856
10461036, -76, -77, 10479063;
CUMMINS 3675127RX;
FORD E8HT-11001-AA, -BA,
E8HZ-11002-A, -HA, F6HZ-11002-BA;
WESTERN STAR
820013436;



SDR0077
For 42MT Series
DD: 12-Volt;
CW: 11-Tooth;
Lester 6503, 6551;
PIC 142-217, -8;

5/8 Inch Mounting Holes
Reversed Terminals
USED ON:
Various H.D. Applications

REPLACES:
DELCO
1990396, -450, -458, 10461045,
10479150;
VOLVO
422997;



SDR0078
For 42MT Series
DD: 12-Volt;
CW: 12-Tooth;
Lester 6507, 6546;
PIC 142-219H, -220H;

5/8 Inch Mounting Holes
Reversed Terminals
w/Overcrank Protection
USED ON CHEVROLET / GMC:
1984-89 C60, C6D, C70, C7D w/Caterpillar 3208
1984-93 Caterpillar Diesel Engines w/Caterpillar 3208
1984-88 J8C / J9C Bruin w/Caterpillar 3208
1984-90 Topkick / Kodiak w/Caterpillar 3208

REPLACES:
DELCO
1990451, 1993777, -824, 10451065,
10461063, -079, -332;
FORD
F6HT-11001-DA, F6HZ-11002-DA;
MOTORCRAFT
SA-826;



SDR0288
For 37MT Series
DD: 12-Volt;
CW: 10-Tooth;
Lester 6295;
PIC 141-378;

1/2 Inch Mounting Holes
Has Overcrank Protection
USED ON INTERNATIONAL:
1993-04 3000-3900 Series Bus w/IHC 7.3L (T-444E)
1995-97 3000-3900 Series Bus w/IHC NGD-V8
1993-04 4000-4900 Series Medium-Duty w/IHC 7.3L (T-444E)

REPLACES:
DELCO
1993971;



SDR0391
For 41MT Series
DD: 12-Volt;
CW: 12-Tooth;
Lester 6673;
PIC 141-398;

.41 Mounting Holes
Insulated Ground
Has Overcrank Protection
USED ON FORD:
1998-99 L6000 / 7000 / 8000 / 9000 Trucks w/Caterpillar 3126
2000-03 F650 / F750 w/Caterpillar 7.2L (3126)
2004-10 F650 / F750 w/Caterpillar 7.2L (C-7)

REPLACES:
DELCO
10479216, -307;
FORD
XC4Z-11002-AB,
XC4Z-11V002-ABRM;
MOTORCRAFT
SA-1007RM, SA-885;

MARINE



AMT0262
For Mitsubishi
IR/EF; 12-Volt;
50 Amp;
Lester 20061;
PIC 203-5388;

1-V Pulley
P-Terminal on Rear
USED ON:
Mitsubishi Motors
All L2E, L3E Inboard w/L2E-62WM
1982-On K3M Inboard w/ K3M-61EM
1982-On K4E Inboard w/K4E-61DM, K4E-61EM
1982-On K4F w/K4F-61WM, K4F-62WM

REPLACES:
MITSUBISHI
A2T25271;
MITSUBISHI INDUSTRIAL
MM409650;
WESTERBEKE
30594;

MARINE



SAB0132
For Yamaha Marine
PMDD: 12-Volt;
CCW: 9-Tooth;
PIC 106-110;

Rear Mounting Bracket is 8.50mm Wide and 55mm Long
USED ON:
Yamaha 40XWH 40HP Engines

REPLACES:
YAMAHA
66T-81800-00-00, 0-02-00,
-03-00;



TRM9201
Wiring Harness
For Tilt / Trim Motors

USED ON:
Tilt & Trim Motors
AEP TRM0103

REPLACES:
MERCURY MARINE
865770A02;

OUTDOOR POWER EQUIPMENT



SND0468
For Yamaha Small
Engines
PMDD: 12-Volt;
CCW: 9-Tooth;
Lester 19558;
PIC 190-6095;

USED ON:
Kohler CS12-941618 Series Engines
Yamaha Outdoor Power Equipment
EF4000DEX, YG4000DX Models

REPLACES:
DENSO
228000-8740, -1;
KOHLER
63-098-04S;
YAMAHA
7UJ-81800-00-00;

POWERSPORTS



AHA4046
Stator Coil
For Honda ATV

ID 35mm
OD 92mm
Width / Length 16mm
Posts 18
USED ON:
1988-00 TRX300, -FX w/281cc

REPLACES:
HONDA
31120-HC4-003, -750;



AHA4058
Stator Coil
For Honda Scooters

Stack Size: 115mm OD x 53.4mm ID x 24.3mm T
USED ON:
2002 FJS / FSC600 Silver Wing w/582cc
2003-13 FJS / FSC600A Silver Wing w/582cc
2003-10 FJS / FSC600D Silver Wing w/582cc

REPLACES:
HONDA
31120-MEF-003;



AHA4059
Stator Coil
12-Volt;
For Honda ATV

92mm OD x 34.3mm ID x 27.8mm T
(Inner Plastic Piece - 18.2mm Stack Height
Plug #1 (3) Yellow Wires - 29 Inches Long
Plug #2 - (1) Blue, (1) Green, (1) Yellow Wire - 17 Inches Long
Includes Pickup
USED ON:
2009 TRX300X w/281cc
1993-08 TRX300EX w/281cc

REPLACES:
HONDA
31120-HM3-671;



AHA6109
Voltage
Regulator / Rectifier
12-Volt;
For Honda M/C

110mm L x 85mm W x 44mm T
Plug #1 - (3) Yellow Wires - 19 Inches Long - w/Protective Boot
Plug #2 - (2) Red Wires, (2) Green Wires - 16 Inches Long
Mounting Holes 80mm Center-to-Center
USED ON:
2004-07 CB900F 919 (USA) w/919cc
2004-07 CB900F Hornet (Europe) w/919cc

REPLACES:
HONDA
31600-MCZ-D11;
SHINDENGEN
SH689GA;

POWERSPORTS



AHA6110
Voltage
Regulator / Rectifier
12-Volt;
For Honda M/C

110mm L x 86mm W x 42.5mm T
Plug #1 - (3) Yellow Wires - 8 Inches Long
Plug #2 - (2) Red Wires, (2) Green Wires, (1) Black Wire - 15.5 Inches Long
Mounting Holes 80mm Center-to-Center

USED ON:
2002 FJS / FSC600 Silver Wing w/582cc
2002-13 FJS / FSC600A Silver Wing w/582cc
2003-10 FJS / FSC600D Silver Wing w/582cc

REPLACES:
HONDA
31600-MCT-771, -MEF-003;
SHINDENGEN
SH689BB, -HA;



AKY6011
Voltage
Regulator / Rectifier
12-Volt;
For Honda, KYMCO
Scooter

80.3mm L x 80mm W x 30.3mm T
Plug #1 - 128mm OAL - 4-Pin (1 Empty) - Red, Green, Black
Plug #2 - 115mm OAL - 3-Pin - All 3 Yellow Wires
Mounting Holes 65.4mm C-to-C
Notes: Silver Finish

USED ON:
Honda
1985-86 CH150 Elite w/153cc
1985-86 CH150D Elite Deluxe w/153cc
1985-88 CH250 Elite w/244cc
1986-01 CN250 Helix / Fusion / Spazio w/244cc

KYMCO
2000-07 Bet & Win 125/150/250
1997-10 Dink 125 w/125cc
2002-07 Dink Classic 125/150
2005-10 Grand Vista 250 w/250cc
1995-00 Heroism 125/150
2003-07 People 250 w/251cc
2007-13 People S 200i w/163cc
2005-07 Xciting 250 w/249cc
2003-06 Yup 250 w/250cc

REPLACES:
HONDA 31600-KM1-008, -KS4-770,
-KS4-841;
DAELIM 31600-SZ1-900;
KYMCO 00168780, 31600-KAM1-
009, 31600-MK1-008;
MALAGUTI 02601800;
PIAGGIO 495186;
SHINDENGEN SH532A-12;
SYM 31600-H9A-000, -M56-000;

Also Used On Betamotor, Daelim, Malaguti, Piaggio, and SYM in Europe



ASU6029
Voltage
Regulator / Rectifier
12-Volt;
For Suzuki M/C

80mm L x 66mm W x 26.5mm T
Plug #1 - 3 Black Wires (Charging Stator)
Plug #2 - (1) Black w/Red, (1) Black w/White Wires

USED ON:
2004-09 GS500F w/487cc

REPLACES:
SUZUKI
32800-01D00, 32800C01D00J000;
SHINDENGEN
SH640HA;



AYA4034
Stator Coil
For Yamaha ATV

USED ON:
2000-09 Big Bear 400 2WD YFM400 w/386cc
2000-11 Big Bear 400 4WD YFM400F w/386cc
2002-05 Wolverine 350 YFM350FX w/348cc

REPLACES:
YAMAHA
5FU-81410-00-00;



IKI6003
CDI Module
For Kawasaki ATV
Capacitive
Discharge Ignition

USED ON:
1995-00 KEF300 Lakota 300 w/290cc
2001-03 KEF300 Lakota Sport w/290cc
1988-04 KLF300 Bayou 300 w/290cc
1989-05 KLF300 Bayou 300 4x4 w/290cc

REPLACES:
KAWASAKI
21119-1241, -1302, -1369;

POWERSPORTS



SCH0098
For Peugeot, Sym
PMDD: 12-Volt;
CW: 10-Spline;

USED ON:
Peugeot
2010-13 Speedfight 50
2010-13 Tweet 50
2009-10 Ludix Pro 50
2010-13 Vivacity 3L Sixties 50

Sym
2006-13 Mio 50
2009-13 Symphony II, S, SR 50
2009-10 Symply II 50
2009-13 Fiddle II S 50
2012-13 X-Pro
2009-13 Jet 50

REPLACES:
PEUGEOT
801638;
SYM
31200-A1A-000, -AWA-000;



SCH0099
For Piaggio
12-Volt;
CCW: 11-Tooth;

USED ON:
European Models Piaggio Vespa PK50, PK125, APE 50

REPLACES:
PIAGGIO
179116, 1791165;



SMU0183
For Kawasaki M/C
PMDD: 12-Volt;
CCW: 10-Spline;
Lester 18691, 18834;
PIC 191-330, -B;

USED ON:
1985 VN700 LTD w/700cc
1985-06 VN750 Vulcan 750 w/749cc

REPLACES:
KAWASAKI
21163-1068, -1319;



SSW2912
Angle Sensor
For Honda

USED ON:
2004-07 TRX400FA FourTrax Rancher AT w/397cc
2004-07 TRX400FGA FourTrax Rancher AT w/397cc
2001-14 TRX500FA FourTrax Foreman Rubicon w/499cc
2006-08 TRX500FGA FourTrax Foreman Rubicon w/499cc
2004-05 TRX500FGA FourTrax Rubicon w/499cc
2009-14 TRX500FPA FourTrax Rincon GPS w/475cc

REPLACES:
HONDA
06380-HN2-305,
38800-HN2-000, -005, -015;

COMPONENTS



SMU5016
Drive Assy.
CW: 9-Tooth;
For Acura, Honda
Starters

USED ON:
Lester 17816, 17844;

WE KEEP YOU RUNNING

MAIN LOCATION
CALL: (800) 328-5454
FAX: (763) 255-2530
3787 95th Ave. NE
Blaine, MN 55014

EAST COAST
CALL: (855) 214-0712
FAX: (508) 857-0586
145 Bodwell Street
Avon, MA 02322

WEST COAST
CALL: (800) 457-1728
FAX: (209) 537-2856
821 Oates Court
Modesto, CA 95358

CANADA
CALL: (877) 617-2888
FAX: (416) 645-1972
398 Canarctic Drive
North York, Ontario M3J 2V3