



NEW PRODUCTS

MAIN LOCATION 800.328.5454 | EAST COAST 855.214.0712 | WEST COAST 800.457.1728 | CANADA 877.617.2888

AG / INDUSTRIAL



ADR0351
For 10DN Series
ER/EF; 12-Volt;
55 Amp;
Lester 7155;
PIC 240-141A;

Delco 10DN Alternator
Clock Position 3
Alternator Only - Tach Drive Not Included

USED ON ALLIS CHALMERS:

Industrial Tractors
1970-72 I-918 w/2900 Dsl
Farm Tractors
1970-75 160 w/3-152 Dsl
1970-73 170 w/4-226 Gas
1970-80 175 w/4-226 Gas
1970-73 170 w/4-236 Dsl
1970-80 175 w/4-236 Dsl
1968-73 180 w/6-301 Dsl
1970-81 185 w/6-301 Dsl

REPLACES:
N/A

1968-72 190 w/6-301 Dsl
1972-75 200 w/6-301 Dsl
1969-74 180 w/6-301 Gas
1964-71 190XT w/6-301 Gas
1970-73 210 w/6-426 Dsl
1970-73 220 w/6-426 Dsl



ADR0457
For 11SI Series
IR/IF; 12-Volt;
95 Amp;
Lester 8729;
PIC 240-6349;

8-Groove Pulley 55mm OD
Clock Position 9
Top Ear 8mm x 1.25

USED ON:
Cummins Applications

Bottom Ear 10mm
Terminals PLIS

REPLACES:
DELCO
8600030;



ADR0463
For 36SI Series
IR/EF; 24-Volt;
60 Amp; BI;
Lester 8584;
PIC 240-917;

Delco 36SI Alternator
w/Remote Sense
1/4 Inch Battery Stud
Pin R-Terminal

USED ON:
Caterpillar Applications

No I-Terminal
Insulated Ground
Terminals PLIS

REPLACES:
DELCO
8600400, -721;
CATERPILLAR
10R8877, 333-1184;



ADR0464
For 13SI Series
IR/IF; 24-Volt;
50 Amp;
Lester 8730;
PIC 240-902;

Delco 13SI Alternator
Clock Position 1
Top Ear 8mm x 1.25 Threaded
Bottom Ear 11.5mm Unthreaded

USED ON:
Cummins Engines

8-Groove Pulley
Plug P-L-F-S

REPLACES:
DELCO
8600365;
CUMMINS
3972731;

AG / INDUSTRIAL



ADRO465
For 13SI Series
IR/IF: 24-Volt;
50 Amp;
Lester 8865;
PIC 240-904;

Delco 13SI Alternator
Clock Position 1
Top Ear Unthreaded (9.5mm)
Plug Code P-L-F-S
USED ON:
Caterpillar

REPLACES:
DELCO
8600075, -282;
CATERPILLAR
327-6712;
PERKINS
2871A502;



AIA0033
For JCB
IR/IF: 24-Volt;
55 Amp;
Lester 20722;
PIC 282-746;

USED ON:
JCB Dieselmax, Ecomax Applications

REPLACES:
LETRIKA
IA 1211;
MAHLE
MG69;
JCB
320/08611, -50;



AIA0035
For Caterpillar,
John Deere, Timberjack
IR/EF: 12-Volt;
75 Amp;
PIC 282-221;

8-Groove Pulley
USED ON:
Caterpillar Backhoes
John Deere Applications
Timberjack Skidders

REPLACES:
LETRIKA
IA 1299;
MAHLE
MG482;
JOHN DEERE
RE505895, SE502626;



AIA0036
For AGCO,
Massey Ferguson
IR/EF: 12-Volt;
120 Amp;
Lester 20723;
PIC 282-668;

USED ON:
AGCO Tractors
AGCO Challenger Tractors
Massey Ferguson MF 6445 90HP, MF 6455 100HP,
MF 6460 115HP, MF 6470 125HP
And Many More

REPLACES:
LETRIKA
IA 1320;
MAHLE
MG182;
AGCO
4287014F1, M1, M2, M3, M4;



AIA0037
For Renault
IR/IF: 12-Volt;
95 Amp;
Lester 12547;
PIC 282-408;

1-V Pulley 80mm OD
USED ON:
1998-On Renault Ceres 75, 85, 95 Tractors

REPLACES:
LETRIKA
IA 0668;
MAHLE
MG234;
RENAULT
7700036536;



AIA0038
For Claas, Renault
Tractors
IR/IF: 12-Volt;
120 Amp;
Lester 24097;
PIC 282-166;

USED ON:
Claas, Renault Tractors, Agricultural Applications

REPLACES:
LETRIKA
IA 0668;
MAHLE
MG234;
CLAAS
7700071558;
RENAULT
7700036536;

AG / INDUSTRIAL



AND0229

For Toyota
IR/IF: 12-Volt;
50 Amp;

Lester 12181;
PIC 290-184;

1-V Pulley 76mm OD;
USED ON TOYOTA LIFT TRUCKS:
1986-89 5FD-20, -23, -25 w/J2 Engine
1988 5FG-33, -35, -38 w/F3 Engine
1988 5FG-40, -45 w/F4 Engine

REPLACES:
DENSO
100211-4200, -1;
TOYOTA
27070-23040, -0-71;



AND0236

For Kubota Engines
IR/IF: 24-Volt;
20 Amp;

Lester 12201;
PIC 290-173;

USED ON:
Kubota V1200 Engines in Agricultural Applications

REPLACES:
DENSO
100211-4310;
KUBOTA
19883-64011;



AND0623

For Caterpillar
IR/EF: 24-Volt;
150 Amp;
Remanufactured;

Lester 12859;
PIC 290-5650;

Denso Brushless Alternator
J-180 Mount
USED ON:
2007-12 Caterpillar 928HZ Wheel Loaders w/Cat. C6.6

REPLACES:
DENSO
021080-0680, 101210-9000, -1;
CATERPILLAR
10R-9097, 249-0313;



AND0645

For Cummins
IR/IF: 24-Volt;
60 Amp;

Lester 20637;
PIC 290-5712;

2-V Pulley
Clock Position 12
USED ON:
Cummins Engines

REPLACES:
DENSO
102211-4080;
CUMMINS
4945839;
KOMATSU
600-861-6510;



APR0037

For KHD
IR: 24-Volt;
40 Amp; BI;

Lester 12710;
PIC 208-408, -12;

USED ON:
KHD Industrial Engines

REPLACES:
VALEO
439101, -91;
PARIS RHONE
A13N257, -72;
KHD
117-8347, -9756, -9756KZ, -9898,
118-0650;



SBO0365

For Lombardini
PMGR: 12-Volt;
CCW: 11-Tooth;

PIC 120-5100;

USED ON:
Agricultural Applications

REPLACES:
BOSCH
0-001-107-090;
LOMBARDINI
563R0780;

AG / INDUSTRIAL



SBO0370
 For Sabb, Others
PMGR: 12-Volt;
CCW: 9-Tooth;
 Lester 32074, 32075,
 32076, 32077;
 PIC 120-039, -A,
 120-6106, -D;

Diesel Inboard Engine
 Also Replaces Bosch DD Units Shown
USED ON:
 1976-83 Sabb H / HG w/0.6L Engine
 1966-83 Sabb 2H / 2GH w/1.2L Engine
 Also Used on Claas, Lombardini Engines in
 Agricultural and Industrial Applications

REPLACES:
BOSCH
 0-001-109-012, -307-024, -311-056,
 -314-016;
CLAAS
 6034870;
LOMBARDINI
 58401750;
MARELLI
 MSN2022;



SIA0016
 For John Deere
PLGR: 12-Volt;
CW: 10-Tooth;
 Lester 18476;
 PIC 182-167;

USED ON JOHN DEERE FARM TRACTORS:
 All 5045D / 5045E w/JD 3-179 45HP Dsl
 All 5203 / 5215 / 5215F&V w/JD 3-179 56HP Dsl
 All 5303 / 5310 / 5310N w/JD 3-179 64HP Dsl
 All 5315 / 5315F&V w/JD 3-179 66.5HP Dsl
 All 5410 / 5410N w/JD 4-276 81HP Dsl
 All 5090G w/JD 4-276 90HP Dsl
 And Many More

REPLACES:
LETRIKA
 IS 1059;
JOHN DEERE
 RE501713, -16455, -9568,
 SE501869;
MAHLE
 MS430;



SIA0018
 For Cummins, Ford,
 Kenworth, Ottawa
PLGR: 12-Volt;
CW: 10-Tooth;
 PIC 182-561;

USED ON:
 Cummins, Ford, Kenworth, Ottawa

REPLACES:
LETRIKA
 IS 1090;
MAHLE
 MS148;



SIA0019
 For Landini
PLGR: 12-Volt;
CW: 10-Tooth;
 Lester 32561;
 PIC 182-564;

With Perkins 1004-40, -42 Engines
USED ON:
 All AGCO Challenger MT364 Farm Tractors w/Perkins Dsl

REPLACES:
LETRIKA IS 1098;
AGCO 191068M94, 4270745M2,
 1482841M92, 3667037M91;
CASE 234987A1;
LANDINI 3542185M93, 3667037M91;
MAHLE MS4;
PERKINS 234987A1, 1447834M91;

AUTO



ABO0390
 For Volvo
IR/IF: 12-Volt;
150 Amp;
 Lester 11347;
 PIC 220-5477;

5-Groove Clutch Pulley 56mm OD
 Clock Position 2
USED ON:
 2008-11 Volvo C30 w/2.5L
 2007-11 Volvo C70 w/2.5L
 2007-11 Volvo S40 w/2.4L, 2.5L
 2007-11 Volvo V50 w/2.4L, 2.5L

REPLACES:
BOSCH
 0-121-615-014, -114;
FORD
 6M5T-10300-SA;
VOLVO
 30773111, 36000207, -7-0;



ABO0405
 For Mini Cooper
IR/IF: 12-Volt;
150 Amp;
 Lester 11335, 23561;
 PIC 220-5378, -97;

6-Groove Clutch Pulley 49.5mm OD
 Clock Position 4
USED ON:
 2006-13 Cooper w/1.6L
 2008-14 Cooper Convertible w/1.6L
 2006-13 Cooper S w/1.6L
 2008-15 Cooper S Convertible w/1.6L
 2009-15 Cooper S JCW w/1.6L
 2009-15 Cooper S JCW Convertible w/1.6L

REPLACES:
BOSCH
 0-121-615-012, 0-125-711-011, -078;
BMW
 12-31-7-553-009, -562-388, -574-
 365, -575-872, -604-782, -613-445;
PEUGEOT
 5750 JG;

AUTO



AB00477
For Mercedes Benz
IR/IF: 12-Volt;
150 Amp;
Lester 14051;
PIC 220-5464A;

6-Groove Pulley 50mm OD
USED ON:
2008-12 C300 w/3.0L
2010-12 GLK350 w/3.5L

REPLACES:
BOSCH
0-124-525-171;
MERCEDES BENZ
000-906-12-02, 013-154-63-02;



AB00481
For Audi
IR/IF: 12-Volt;
140 Amp;
Lester 11721;
PIC 220-5788;

6-Groove Clutch Pulley 56mm OD
Clock Position 1
USED ON:
2011-15 TT w/2.0L

REPLACES:
BOSCH
0-124-525-187, -542;
VOLKSWAGEN
03L-903-023;



ACR0003
For Chrysler, Dodge,
Plymouth
ER/IF: 12-Volt;
78 Amp;
Lester 7024;
PIC 230-111, -A, -B, -C, -D;

1-V Pulley
Revised Squareback
Double Field
USED ON:
1970-83 Chrysler
1970-87 Dodge
1970-87 Plymouth

REPLACES:
CHRYSLER
3438701, -2, -3, 3438803, -4, -6, -7,
3579224, 3656217, -8, -9, 3656449,
-451-, -456-, -471-, -614-, -615-, -645,
3752230, 3755192, -3, 3755403,
-04, -05, -06, -07, -14, 3780588,
3874695, -6, -7, -8, 4091563, -4,
-5, -6, 4091727, -95, 4111928, -44,
4176002, -7, 4289689, -975;



ACR0004
For Chrysler, Dodge,
Plymouth
ER/IF: 12-Volt;
78 Amp;
Lester 7509;
PIC 230-102, -A, 230-
109, 230-110, -A, -B, -C;

2-V Pulley
Revised Squareback
Double Field
USED ON:
1970-87 Chrysler
1970-87 Dodge
1970-87 Plymouth

REPLACES:
CHRYSLER
3579222, 3780589, 4121101, 3438176,
-77, -78, -79, -80, -83, -84, 3438704,
-809, -811, -813, 3621853, -61, -67,
3656450, -459, -513, -570, -711, -713,
3755191, -411, -413, -447, 3874699,
-700, -701, -776, -777, 3895326, -641,
4091568, -569, -572, -647, 4111204,
-26, 4176004, -006, -094, -206;



ACR0005
For Chrysler
ER/IF: 12-Volt;
110 Amp;

2-V Pulley
Special 110A Version of ACR0004
USED ON:
1970-87 Chrysler
1970-87 Dodge
1970-87 Plymouth

REPLACES:
N/A



AND0373
For Jaguar
IR/IF: 12-Volt;
120 Amp;
Lester 13909;
PIC 290-5053;

6-Groove Pulley
S-FR-IG-L Plug
USED ON:
2000-02 Jaguar S-Type w/4.0L

REPLACES:
DENSO
102211-0520;
FORD
XR83-10300-AB;
JAGUAR
XR8-6934;

AUTO



AND0472
For GM, Suzuki
IR/IF; 12-Volt;
150 Amp;
Remanufactured;
Lester 11250;
PIC 290-5074, -490,
-490A;

6-Groove Pulley 57mm OD
 L-F Plug
 Clock Position 1
USED ON:
 2008-17 Chevrolet Equinox w/3.6L V6
 2008-12 Chevrolet Malibu w/3.6L V6
 2013-16 GMC Terrain w/3.6L V6
 2008-09 Pontiac Torrent w/3.6L V6

2008-09 Saturn Aura w/3.6L V6
 2008-09 Saturn VUE w/3.6L
 2007-09 Suzuki XL-7 w/3.6L

REPLACES:
DENSO 104210 -2890, -5250, -5251,
 -5410;
GENERAL MOTORS 15807948,
 20841889, 23119515, 96673483;
SUZUKI 31400-78J00;



AND0484
For Acura, Honda
IR/IF; 12-Volt;
130 Amp;
Remanufactured;
Lester 11391;
PIC 290-5222B;

6-Groove Pulley 65mm OD
 C-FR-IG-L Square Plug
 Clock Position 11
USED ON:
 Acura Honda
 2010-13 MDX w/3.7L 2008-10 Odyssey w/3.5L
 2009-12 RL w/3.7L 2009-11 Pilot w/3.5L
 2009-14 TL w/3.5L, 3.7L 2009-11 Ridgeline w/3.5L
 2010-14 TSX w/3.5L
 2010-13 ZDX w/3.7L

REPLACES:
DENSO
 104210-5920;
HONDA
 06311-RGW-505, 31100-RGW-A01;



AND0634
For Honda
IR/IF; 12-Volt;
120 Amp;
Remanufactured;
Lester 11768;
PIC 290-6316;

7-Groove Pulley 59mm OD
 Clock Position 10
USED ON:
 2012-15 Honda Accord Crosstour w/2.4L

REPLACES:
DENSO
 104210-1490;
HONDA
 31100-5J0-A01, CSJ49;



AND0635
For Honda
IR/IF; 12-Volt;
120 Amp;
Remanufactured;
Lester 11604;
PIC 290-5628;

7-Groove Pulley 59mm OD
 Single LIN Plug
 Clock Position 10
USED ON:
 2012-15 Honda Civic w/2.4L
 2012-14 Honda CR-V w/2.4L
 2013-15 Honda ILX w/2.4L

REPLACES:
DENSO
 104210-1530;
HONDA
 31100-RX0-A01, CSJ53;



AND0638
For Toyota
IR/IF; 12-Volt;
130 Amp;
Remanufactured;
Lester 11384, 11403;
PIC 290-5540, -56;

6-Groove Pulley 57mm OD
 Clock Position 12
USED ON:
 2009-13 Toyota Highlander w/2.7L
 2009-16 Toyota Venza w/2.7L

REPLACES:
DENSO
 104210 -2350, -351, -560;
TOYOTA
 27060-0V020, -36030;



AND0639
For Toyota
IR/IF; 12-Volt;
100 Amp;
Remanufactured;
Lester 11400, 11408;
PIC 290-5550, -5;

6-Groove Pulley 57mm OD
 Clock Position 12
USED ON:
 2009-11 Toyota Highlander w/2.7L

REPLACES:
DENSO
 104210-2550, -610;
TOYOTA
 27060-0V070, -36020;

AUTO



SBO0371
For Dodge, Jeep
PMGR: 12-Volt;
CW: 10-Tooth;
Lester 10879;
PIC 120-5010;

USED ON:
2014-16 Dodge Ram 1500 Pickup w/3.0L V6 Dsl
2014-15 Jeep Grand Cherokee w/3.0L V6 Dsl

REPLACES:
BOSCH
0-001-109-403, -4;
CHRYSLER
68080460AA;



SHI0209
For Fiat, Jeep
PMGR: 12-Volt;
CW: 10-Tooth;
Lester 19297;
PIC 104-495;

B+ Stud On Solenoid 22mm OAL
Top RH Mtg. Ear 8mm x 1.25
Bottom RH Mtg. Ear 9mm Unthreaded
Top RH Mtg. Hole Locating Pin 8mm OD
USED ON:
2014-15 Fiat 500L w/1.4L
2015-16 Jeep Renegade w/1.4L L4

REPLACES:
HITACHI
S114-943A;
CHRYSLER
68201259AA;
FIAT
51890631;



SHI0211
For Infiniti
PMGR: 12-Volt;
CW: 12-Tooth;
Lester 19067;
PIC 104-311, -A, -B;

USED ON:
2008-11 EX35 w/3.5L
2009-12 FX35 w/3.5L
2007-08 G35 w/3.5L
2009-10 M35 w/3.5L

REPLACES:
HITACHI
S114-927, -A;
NISSAN
23300-JK20A, -B, -BR, -C;



SMT0439
For Smart
PMDD: 12-Volt;
CCW: 8-Tooth;
Lester 19624;
PIC 103-5174;

USED ON:
2008-13 Smart Fortwo w/1.0L

REPLACES:
MITSUBISHI
MOT46171;
MERCEDES BENZ
132-151-00-01, A132-151-00-01;



SMT0441
For Chevrolet
PMGR: 12-Volt;
CW: 12-Tooth;
Lester 19230;
PIC 103-543;

USED ON:
2012-16 Caprice w/3.6L V6
2013 Impala w/3.6L V6

REPLACES:
MITSUBISHI
MOT35276, -7;
GENERAL MOTORS
92223942, -70149;



SMT0442
For Nissan
PMGR: 12-Volt;
CW: 10-Tooth;
Lester 19123;
PIC 103-5185;

USED ON:
2010-15 Armada w/5.6L
2011-15 Titan w/5.6L

REPLACES:
MITSUBISHI
M1T30871;
NISSAN
23300-ZV00A;



SND0805
For Audi
PMGR: 12-Volt;
CW: 11-Tooth;
Lester 10982;
PIC 190-6089;

USED ON:
2012-13 A6 w/2.0L
2014-16 Q5 w/2.0L Hybrid

REPLACES:
DENSO
428000-7931, -2;
VOLKSWAGEN
06H-911-024A, -B;

AUTO



SVA0002
For Audi, Volkswagen
PMGR: 12-Volt;
CW: 9-Tooth;
Lester 17888;
PIC 108-467, -70;

USED ON:
2004-06 Audi A8 w/4.2L
2005-07 Audi A8 w/6.0L
2004-09 Volkswagen Touareg w/4.2L
2006-08 Volkswagen Touareg w/5.0L Dsl

REPLACES:
VALEO
D7GS7, -17;
VOLKSWAGEN
077-911-023J, -JX, -K;

HD TRUCKS



SMT0454
For Volvo
PLGR: 24-Volt;
CW: 12-Tooth;
Lester 19831;
PIC 103-5115A;

USED ON:
2002-On Volvo D16C

REPLACES:
MITSUBISHI
M9T82671, -2;
VOLVO
20450305, 20732404, 85000295;



SND0631
For Chevrolet, Isuzu
OSGR: 12-Volt;
CW: 11-Tooth;
Lester 18136;
PIC 190-819;

USED ON:
1994-02 Chevrolet and Isuzu Trucks w/Isuzu Engines

REPLACES:
DENSO
228000-2800, -1, -2, -3, -4, -5, -7;
GENERAL MOTORS
94052837;
ISUZU
1811002990, 2911234200,
8975002310, -580, -581;

MARINE



AIA0032
For Volvo-Penta,
Others
IR/EF: 12-Volt;
70 Amp;
Lester 13068;
PIC 282-690;

USED ON:
Volvo-Penta Marine, Others

REPLACES:
LETRIKA
IA 1438;
MAHLE
MG77;
VOLVO
3803260-3, 8722357;
VOLVO PENTA
872019-5, 873633, -770;



AMT0299
For Volvo-Penta
IR/IF: 24-Volt;
80 Amp;
PIC 203-044;

8-Groove Pulley 72mm OD
USED ON:
Volvo-Penta Marine

REPLACES:
MITSUBISHI
A3TR5092;
VOLVO
3587218, 38038045;



AMT0300
For Volvo-Penta
IR/IF: 24-Volt;
80 Amp;
PIC 203-045;

6-Groove Pulley 47mm OD
USED ON:
Volvo-Penta Marine

REPLACES:
MITSUBISHI
A3TR5093;
VOLVO
3840183;

MARINE



TRM6004
Tilt / Trim Relay
For Yamaha

Mounting Holes 6.6mm OD
Mounting Holes 92mm C-to-C
Studs: M6 x 1.0

USED ON:

Yamaha Tilt Motors
(May Fit Others Also)
Yamaha 2-stroke
1994-On 40HP 1992-On 50HP 1992 60HP, 70HP, 85HP, 90HP
Yamaha 4-stroke
2001-On F30 1999-On F40 1995-On F50 2002-On F60

REPLACES:

YAMAHA
6H1-81950-00-00, -01-00;



TRM6005
Relay Assy.
For Yamaha

USED ON:

1999-04 Yamaha Tilt Motors
(May Fit Others Also)
2003-04 F75TLR 1999-03 F80TLR 2003-04 F90TJR 1999-03 F100TLR
2002-03 F80TJR 1999-00 F80TXR 2003-04 F90TLR 1999-03 F100TXR

REPLACES:

YAMAHA
6E5-8195B-01-00;



TRM6006
Relay Assy.
For Yamaha

USED ON:

1999-04 Yamaha Tilt Motors
(May Fit Others Also)
2003-04 F75TLR 1999-03 F80TLR 2003-04 F90TJR 1999-03 F100TLR
2002-03 F80TJR 1999-00 F80TXR 2003-04 F90TLR 1999-03 F100TXR

REPLACES:

YAMAHA
6E5-8195C-01-00;

POWERSPORTS



AKM6003
Voltage
Regulator / Rectifier
12-Volt;
For KTM M/C

USED ON:

2012-15 250 EXC-F w/249cc
2012-15 250 EXC-F Six Days w/249cc
2012-15 250 XCF-W w/249cc
2012-15 350 EXC-F w/350cc
2012-15 350 EXC-F Six Days w/350cc 2012-15 450 XC-W w/449cc
2012-15 350 XC-FW w/350cc 2012-15 500 EXC w/510cc
2012-15 450 EXC w/449cc 2012-15 500 EXC Six Days w/510cc
2012-15 450 EXC Six Days w/449cc 2012-15 500 XC-W w/510cc
2014-15 450 Rally Replica w/449cc 2012-15 Freeride 350 w/350cc

REPLACES:

KTM
78111034000;
SHINDENGEN
SH830AA;



AKY6012
Voltage
Regulator / Rectifier
12-Volt;
For Arctic Cat ATV

80mm L x 80mm W x 31mm T

Plug #1 - (3) Yellow Wires (Charging Coil) - 5 Inches OAL
Plug #2 (1) Red, (1) Black, (1) Green Wire - 15.5 Inches OAL
2 Round Mounting Holes 73mm (Outer), 58.8mm (Inner)

USED ON:

2006-08 250 DVX w/249cc
2009-15 300 DVX 2x4 w/270cc

REPLACES:

ARCTCO
3304-681;



ESP2469
Voltage
Regulator / Rectifier
12-Volt;
For Yamaha M/C

90mm L x 80mm W x 28mm H
Espel Brand

USED ON:

2016-On Yamaha XV250
1997-15 Yamaha Virago XV125
1996-07 Yamaha Virago XV250
2008-15 Yamaha V-Star XV250

REPLACES:

YAMAHA
3DM-81960-00, -1;

POWERSPORTS



SMU0561
For Honda M/C
PMDD; 12-Volt;
CCW; 9-Tooth;
PIC 191-068;

USED ON:
2013-16 Honda CRF125F w/125cc
2014-16 Honda CRF125FB w/125cc

REPLACES:
HONDA
31200-K28-911;



SMU6179
Starter Relay
12-Volt;
For Arctic Cat ATV,
Kymco ATV, Scooters

USED ON:
2017 Arctic Cat 90 Alterra w/89cc ATV
2006-16 Arctic Cat 90 DVX w/89cc ATV
2006-16 Arctic Cat 90 Utility w/89cc ATV
2007-14 Kymco Mongoose 70 w/69cc ATV
2004-10 Kymco Mongoose 90 w/89cc ATV
2000-06 Kymco Filly 50 LX w/50cc Scooters
2006-13 Kymco People S 50 4T w/49cc Scooters
2008-12 Kymco Sento 50 w/50cc Scooters
All Kymco Top Boy 100 w/100cc Scooters

REPLACES:
KYMCO
38500-KKDK-900;
ARCTCO
3303-143;

REFRIGERATION



AVA0165
For Valeo
IR/IF; 12-Volt;
70 Amp;
Lester 11847;
PIC 208-347;

1-V Pulley 89mm OD
CCW Rotation
Left-Hand Threads On Rotor Shaft
Pulley For 13mm Belt
USED ON:
Refrigeration Applications

REPLACES:
CARRIER TRANSICOLD
30-01114-07;
LEECE NEVILLE
A1738B;

COMPONENTS



130-01135
Bearing
B17-127DG
PIC 6730-033;

17mm ID x 62mm OD x 20mm W
USED ON:
Bosch 468, 469 Series IR/EF Alternators (D.E.)
Iskra 150-200 Amp Alternators (D.E.)
Lester 12596, 12597, 12706, 12804;

REPLACES:
BOSCH
1-120-905-097;
KHD
131-9812;
REFERENCE NUMBER
B17-127DG;



172-52064
Rectifier
For Denso
PIC 7790-4060;

OD Mtg Distance: 138mm w/Trio
(8) 50A Press Fit Diodes Output Stud Size: 5/16-18
USED ON:
Denso Brushless Alternators
Lester 12344, 12350M, 12464M, 12669, 12670, 12770;

REPLACES:
DENSO
021580-6150;



202-12006
Pulley, 2-Groove
For Delco
PIC 7940-1194;

#G 2 OAL 39.9mm
OD of Pulley 71.4mm ID 17mm
Notes: 13mm Belts
USED ON:
Delco Alternators

REPLACES:
DELCO
1962505;

COMPONENTS



206-52021
Pulley, 6-Groove
For Denso

OEM Litens Pulley
#G 6
OD of Pulley 60mm
Rib OD 52mm
Notes: Decoupler Pulley

L 45mm
ID 17mm
ROT CW
Screw

REPLACES:
LITENS / TENDECO
920972;
CHRYSLER
05184692AB, 5184692AB;

USED ON:

Denso Alternators On Chrysler & Dodge Applications
Lester 11592, 11792;



208-24001
Pulley, 8-Groove
For John Deere

#G 8
OD of Pulley 66.4mm
Rib OD 59.9mm
L 43.9mm

ID 17mm
ROT N/A
Screw N/A

REPLACES:
JOHN DEERE
R501486;

USED ON:

John Deere Equipment
Lester 12373;



220-44059
Drive Assy.
CW; 9-Tooth;
For Hitachi

Gear Teeth: 9
Gear OD: 35.3mm
Rotation: CW
Clutch Gear Teeth: 41

Clutch Gear OD: 53.25mm
OAL: 100.3mm
Clutch Type: OSGR Type
Splines: N/A

REPLACES:
HITACHI
2130-35008;

USED ON:

Samsung Excavators With Hitachi Starters
Lester 18491;



220-48066
Drive
CW; 9-Tooth;
For Nissan
PIC 6103-2677;

Gear Teeth: 9
Gear OD: 29.6mm
Gear ID: 10.7mm
Rotation: CW

OAL: 68mm
Clutch Type: Roller
Splines: 9

REPLACES:
MITSUBISHI
M191T12971;
NISSAN
23354-W9810;
ZEN
1592, 1.01.1592.0;

USED ON:

Nissan Lift Trucks
Lester 17425, 17437, 17683, 17685, 17738, 18395, 18973,
31120, 32693;



245-12050
Solenoid
24-Volt; 3-Terminal;
For Delco
PIC 6640-165;

Battery Terminal 3/8-16 Relay Terminal None
Motor Terminal 3/8-16
Switch Terminal 8-32 Stud (RH)
Notes: Grounded Base

USED ON:

Delco 30MT, 35MT Starters
Lester 3722, 3874, 3879, 3965, 3967, 4049;

REPLACES:
DELCO
1115505, -11, -42, -77, -86, 1119820,
-84, -96;
ACCUMAX
10A-D944, -4W;



245-12153
Solenoid
12-Volt; 3-Terminal;
For Delco
PIC 6640-431;

Battery Terminal 12mm x 1.75
Motor Terminal 8mm x 1.25
Switch Terminal 5mm x 0.8 Stud (LH)
Relay Terminal None

USED ON:

Delco 29MT Starters
Lester 6838, 6843, 6844;

REPLACES:
DELCO
10515839;

COMPONENTS



245-12157
Solenoid
12-Volt; 4-Terminal;
For Delco

PIC 6640-431;

Battery Terminal 1/2-13 x 2-1/4 (RH)
Motor Terminal 1/2-13 x 1-3/4 (LH)
Switch Terminal 10-32 Stud (RH - Top)
Relay Terminal None
Ground Terminal 10-32 Stud (LH - Top)

USED ON:

Delco 40MT, 50MT Starters

Notes: Square Face
Notes: Semi Solid Link Design
Notes: Insulated Ground

REPLACES:

DELCO
1115715;



AB05001
Pulley, 1-Groove
For Bosch

PIC 7920-1011;

#G 1
OD of Pulley 73mm
Rib OD N/A
L 49.3mm

USED ON:

Bosch Alternators on Audi & VW Applications

Lester 13054, 13055, 13093, 13094, 13109, 13129, 13147, 14396, 14409, 14410, 14412, 14603, 14778, 14779, 14797, 14816, 14970, 14997, 20094, 20296, 20782, 20785, 23587, 23588, 23630, 23734;

ID 17mm
ROT N/A
Screw N/A

REPLACES:

BOSCH
1-126-600-154, -222, -262, -265,
-308, -309, -345, -348, -488, -544;



AFD5034
Pulley, 6-Groove
For Ford

PIC 7950-2274;

#G 6
OD of Pulley 81mm
Rib OD 75mm
L 28.3mm

USED ON:

Ford 4G Series Alternators
Lester 7780A, 8269;

ID 17mm
ROT N/A
Screw N/A

REPLACES:

FORD
GP736, YF1U-10A352-AA,
YF1Z-10346-E;
MOTORCRAFT
GP736;



AND1056
Alternator Cover

USED ON:

Used on Denso Alternators
Lester 13547, 13687, 13791;

REPLACES:

DENSO
021551-2431;



AND5014
Pulley, 2-Groove
For Toyota

PIC 7990-9030;

USED ON:

1982-83 Toyota Celica Supra
1981-83 Toyota Cressida
Lester 13168, 13169, 14337, 14573, 14574;

REPLACES:

N/A

WE KEEP YOU RUNNING



MAIN LOCATION

CALL: (800) 328-5454
FAX: (763) 255-2530
3787 95th Ave. NE
Blaine, MN 55014

EAST COAST

CALL: (855) 214-0712
FAX: (508) 857-0586
145 Bodwell Street
Avon, MA 02322

WEST COAST

CALL: (800) 457-1728
FAX: (209) 537-2856
821 Oates Court
Modesto, CA 95358

CANADA

CALL: (877) 617-2888
FAX: (416) 645-1972
398 Canarctic Drive
North York, Ontario M3J 2V3

The information herein is based upon data which we believe to be correct and believe to have been obtained from reliable sources, but no representation is made herein, nor should any be implied, regarding the accuracy of any such information and we assume no liability for any errors or omissions in any such information. Any original equipment manufacturers or other manufacturers or distributors, whose names, numbers, pictures, symbols, products and/or descriptions are, or may be, listed or shown herein are used for reference purposes only and there is no representation made or intended, nor should any be implied, that any item reference herein is the product of, or was manufactured and/or distributed, by, the referenced manufacturer or distributor, as the case may be. This brochure is intended for reference purposes only. For pricing or terms and conditions, please refer to your price sheet.