

NEW PRODUCTS

MAIN LOCATION 800.328.5454 | WEST COAST 800.457.1728 | CANADA 877.617.2888

AG / INDUSTRIAL



ADR0152-C
For 10SI Series
IR/EF; 12-Volt; 63 Amp;
Lester 7127-SEC;
PIC 240-204C;

Chrome Version
STD 1-V Pulley

Clock Position 3
1-Wire Hookup

REPLACES:
N/A

This is a 1-Wire (Self-Exciting) 10SI Type Alternator Which Can Be Used in Countless Applications Where a Single Battery Connection is Desired. This Alternator is Often Used to Replace Generators on Older Equipment (Mounting Kits May Be Required) Also See ADR0335-C (105A)



SIA0017
For Deutz Engines
PLGR; 12-Volt;
CW; 11-Tooth;
Lester 18230;
PIC 182-468;

USED ON:
Deutz Engines

REPLACES:
LETRIKA
IS 1072;
MAHLE
MS30;



SVA0022
For Hyundai
PMGR; 12-Volt;
CW; 8-Tooth;
Lester 19232;
PIC 108-507;

USED ON:
Forklift & Industrial Applications

REPLACES:
VALEO
1250438;
HYUNDAI
36100-23C00;

AUTO



410-48305
For Infiniti, Nissan
PMGR; 12-Volt;
CCW; 13-Tooth;
Lester 19256;
PIC 103-6541;

USED ON:
2014-16 Infiniti Qx60 w/3.5L
2015-16 Nissan Altima w/3.5L
2015-16 Nissan Maxima w/3.5L
2015-16 Nissan Murano w/3.5L
2015-16 Nissan Pathfinder w/3.5L
2015-16 Nissan Quest Van w/3.5L

REPLACES:
MITSUBISHI
MOTB0271, -1ZC, -2, -2ZC;
NISSAN
23300-4AY0A, -9HPOA, -B,
-BRE;

AUTO



410-48306

For Nissan
PMGR: 12-Volt;
CW: 10-Tooth;

Lester 19137;
PIC 103-5169;

USED ON:

2012-14 Versa w/1.6L
2012 Versa w/1.8L
2014 Versa Note w/1.6L

REPLACES:

MITSUBISHI
MOT32175, -79, -81;
NISSAN
23300-1HK0A, -AR, -B, -C, -CRE;



AB00409

For Mercedes Benz
IR/IF: 12-Volt; 220 Amp;

Lester 11310;
PIC 220-5593;

6-Groove Pulley 50mm OD
Clock Position 12

USED ON:

2009-10 Mercedes Benz CL550 w/5.5L V8
2007-10 Mercedes Benz S550 w/5.5L

REPLACES:

BOSCH
0-121-813-006;
MERCEDES BENZ
013-154-55-02;



AFD0051

For Ford
IR/IF: 12-Volt; 95 Amp;

Clock Position 7

USED ON:

Special Applications Requiring 7:00 Plug Position

REPLACES:

N/A



AMT0270

For Ford
IR/IF: 12-Volt; 150 Amp;

Lester 11551;
PIC 203-5356;

4-Groove Decoupler Pulley 52mm OD
Clock Position 6
Applications wo/Power Point Plug

USED ON:

2013-16 Ford Escape w/2.0L L4 Turbo
2013-16 Ford Escape w/2.5L L4
2013-16 Ford Focus w/2.0L L4
2014-16 Ford Transit Connect w/2.5L L4

REPLACES:

MITSUBISHI
A2TX2581ZC;
FORD
CJ5T-10300-CB,
CJ5Z-10346-C;
MOTORCRAFT
GL-8669;



AND0317

For Cadillac
IR/IF: 12-Volt; 150 Amp;
Remanufactured;

Lester 11038, 11248;
PIC 290-5186, -A;

5-Groove Pulley 59mm OD
Clock Position 8
L-F PLUG

USED ON:

2004-09 Cadillac SRX w/4.6L
2006-09 Cadillac STS w/4.4L
2005-10 Cadillac STS w/4.6L

REPLACES:

DENSO
104210-3261, -4340;
GENERAL MOTORS
25709327, 25756440;



AND0428

For Ford
IR/IF: 12-Volt; 130 Amp;
Remanufactured;

Lester 11238;
PIC 290-5295, -A;

6-Groove Pulley 57mm OD
Clock Position 1
Plug LI-RC-BVS

USED ON:

2005-07 Ford Freestyle w/3.0L V6

REPLACES:

DENSO
104210-4090, -4091, -5300;
FORD
5F9T-10300-BB, 5F9Z-10346-BA,
6F9T-10300-DA;
MOTORCRAFT
GL-604;

AUTO



ANDO471
For Cadillac, Chevrolet, Suzuki
IR/IF: 12-Volt: 170 Amp;
Remanufactured;
Lester 11251;
PIC 290-5073;

6-Groove Pulley 57mm OD
 Clock Position 1
 L-F Plug
USED ON:
 2013-17 Cadillac XTS w/3.6L V6
 2012-13 Chevrolet Impala w/3.6L V6
 2014-16 Chevrolet Impala Limited w/3.6L V6
 2007-09 Suzuki XL-7 w/3.6L

REPLACES:
DENSO
 104210-6010, -1;
GENERAL MOTORS
 15136252, 23106528;
SUZUKI
 31400-78J10;



ANDO475
For Chrysler
ER/IF: 12-Volt: 136 Amp;
Remanufactured;
Lester 11244;
PIC 290-5143A;

4-Groove Pulley 60mm OD
 Clock Position 12
USED ON:
 2006-09 Chrysler PT Cruiser w/2.4L Turbo

REPLACES:
DENSO
 421000-0370, -1;
CHRYSLER
 05034702AA, 5034702AA;



ANDO500
For Dodge
ER/IF: 12-Volt: 140 Amp;
Remanufactured;
Lester 11381;
PIC 290-5387;

6-Groove Pulley 53mm OD
 Clock Position 10
USED ON:
 2009-10 Dodge Journey w/3.5L

REPLACES:
DENSO
 421000-0460;
CHRYSLER
 05033759AC, 5033759AC;



ANDO517
For Dodge
ER/IF: 12-Volt: 160 Amp;
Remanufactured;
Lester 11401;
PIC 290-5585;

6-Groove Pulley 53mm OD
 Clock Position 10
USED ON:
 2009-10 Dodge Journey w/3.5L

REPLACES:
DENSO
 421000-0650;
CHRYSLER
 04801483AA, 4801483AA;



AVA0123
For Hyundai
IR/IF: 12-Volt: 110 Amp;
Lester 11189;
PIC 208-736;

6-Groove Clutch Pulley 60mm OD
 Clock Position 4
USED ON:
 2009-10 Hyundai Sonata w/2.4L

REPLACES:
VALEO
 TG11C076;
HYUNDAI
 37300-2G100;



AVA0128
For Hyundai, Kia
IR/IF: 12-Volt: 90 Amp;
Lester 11452;
PIC 208-232;

4-Groove Pulley 57mm OD
 Clock Position 11
USED ON:
 2010-11 Hyundai Accent w/1.6L
 2010-11 Kia Rio w/1.6L

REPLACES:
VALEO
 2608371;
HYUNDAI
 37300-26100;

AUTO



AVAO161
For Hyundai, Kia
IR/IF: 12-Volt; 100 Amp;
Lester 11493;
PIC 208-963;

6-Groove Clutch Pulley 56.25mm OD
Clock Position 4

USED ON:
2010-12 Hyundai Santa Fe w/2.4L
2011-14 Hyundai Sonata w/2.0L
2012-13 Kia Optima w/2.0L
2011 Kia Sorento w/2.4L

REPLACES:
VALEO
TG11C089;
HYUNDAI
37300-2G600;



AVAO177
For Hyundai
IR/IF: 12-Volt; 130 Amp;
Lester 11111;
PIC 208-5033;

6-Groove Pulley 52mm OD
Clock Position 10

USED ON:
2010 Hyundai Sonata w/3.3L

REPLACES:
VALEO
TG12C057;
HYUNDAI
37300-3C250;



AVAO181
For Nissan
IR/IF: 12-Volt; 130 Amp;
Lester 11256;
PIC 208-215B;

7-Groove Pulley 59mm OD
Clock Position 9

USED ON:
2012-15 Nissan Armada w/5.6L
2013-16 Nissan Frontier Pickup w/4.0L
2016 Nissan NV1500 w/4.0L
2016 Nissan NV2500 HD w/4.0L, 5.6L
2016 Nissan NV3500 HD w/4.0L, 5.6L
2012-15 Nissan Titan w/5.6L
2013-15 Nissan Xterra w/4.0L

REPLACES:
VALEO
TG15S192;
NISSAN
23100-ZH00D;



SDR0434
For Hyundai, Kia
PMGR: 12-Volt;
CW: 11-Tooth;
Lester 6974, 6995;
PIC 140-6026B, -6112;

USED ON:

Hyundai	Kia
2013-14 Genesis Coupe w/2.0L	2011-13 Forte w/2.0L, 2.4L
2013-16 Santa Fe w/2.0L	2011-13 Forte Koup w/2.0L, 2.4L
2014-16 Santa Fe w/2.4L	2011-16 Optima w/2.0L, 2.4L
2011-16 Sonata w/2.0L	2016 Sorento w/2.0L
2015-16 Sonata w/2.4L	2015-16 Sorento w/2.4L
2011-13 Tucson w/2.0L	2013-16 Sportage w/2.0L, 2.4L
2011-15 Tucson w/2.4L	

REPLACES:
DELCO
8000357, -621, -743;
HYUNDAI
36100-2G200, -210, -400;



SVA0007
For BMW
PMGR: 12-Volt;
CW: 9-Tooth;
Lester 17902;
PIC 108-432;

USED ON:

2001-06 M3 w/3.2L
2002 Z3 w/3.2L
2006-08 Z4 w/3.2L

REPLACES:
VALEO
D6RA108;
BMW
12-41-7-830-793, -832-150, -832-486, -834-214, -835-735;



VBO0254
For BMW, Range Rover
IR: 12-Volt; 150 Amp;
Lester 13815;
PIC 220-5075A;

USED ON:

1999-03 BMW 540 Series w/4.4L
1999-01 BMW 740 Series w/4.4L
1999-00 BMW 750 Series w/5.4L
2000-04 BMW X5 w/4.4L
2002-03 BMW X5 w/4.6L
2003-05 Range Rover w/4.6L

REPLACES:
BOSCH
0-122-0AA-110;
BMW
12-31-7-508-052, -4;
LAND ROVER
LR005866, YLE000040;

AUTO



VBO0391
For BMW
IR/IF: 12-Volt; 180 Amp;
Lester 11301;
PIC 220-5481;

6-Groove Clutch Pulley 49mm RIB OD
Clock Position 12

USED ON:
2008-13 BMW 128 Series w/3.0L
2007-09 BMW 323 Series w/2.5L
2007-13 BMW 328 Series w/3.0L
2008-09 BMW 528 Series w/3.0L
2007-10 BMW X3 w/3.0L
2007-10 BMW X5 w/3.0L

REPLACES:
BOSCH
0-121-715-012, -112;
BMW
12-31-7-550-968, -551-256,
-555-926;



VMT0228
For Nissan
IR/IF: 12-Volt; 130 Amp;
Lester 11341, 11557;
PIC 203-5121, -5121A, -364;

7-Groove Pulley 55mm OD
Clock Position 1
L-S-C Plug

USED ON:
2007-16 Nissan Altima w/3.5L
2009-16 Nissan Maxima w/3.5L
2009-14 Nissan Murano w/3.5L
2011-16 Nissan Quest Van w/3.5L

REPLACES:
MITSUBISHI
A3TJ1791, -1791ZC, -3691;
NISSAN
23100-1AA1A, -JA11A,
-JA11AR, -JA11B, -JA11BRE,
2310M-JA11BRW;



VND0249
For Chrysler,
Dodge Minivans
ER/IF: 12-Volt; 160 Amp;
Remanufactured;
Lester 13870;
PIC 290-5118, -A;

6-Groove OVR Pulley 57mm OD
2-Pin Plug

USED ON:
2001-07 Chrysler Town & Country Van w/3.3L, 3.8L
2001-04 Chrysler Voyager Van w/3.3L
2001-07 Dodge Caravan w/3.3L
2001-07 Dodge Grand Caravan w/3.3L, 3.8L

REPLACES:
DENSO
421000-0021, -022, -023,
-024, -025, -026, -027, -028,
-492, -493;
CHRYSLER
4686430AF, -B, -C, -D, -E, -F,
-H;



VND0293
For Chrysler,
Dodge Minivans
ER/IF: 12-Volt; 136 Amp;
Remanufactured;
Lester 13871;
PIC 290-5117, -A;

6-Groove OVR Pulley 57mm OD

USED ON:
2001-07 Chrysler Town & Country Van w/3.3L, 3.8L
2001-04 Chrysler Voyager Van w/3.3L
2001-07 Dodge Caravan w/3.3L
2001-07 Dodge Grand Caravan w/3.3L, 3.8L

REPLACES:
DENSO
421000-0011, -012, -013, -222,
-223, -225;
CHRYSLER
04868431AF, -G, 4868431AB,
-C, -D, -F, -G;



VND0426
For Toyota
IR/IF: 12-Volt; 80 Amp;
Remanufactured;
Lester 11203, 11505;
PIC 290-5276, -A;

4-Groove Pulley 59mm OD
Clock Position 9
Square L-IG-S-M Plug

USED ON:
2006-14 Toyota Yaris w/1.5L

REPLACES:
DENSO
104210-8180, -400;
TOYOTA
27060-21150, -1;

AUTO



VND0494
For Ford Light Trucks, Lincoln
IR/IF: 12-Volt: 150 Amp;
Remanufactured;
Lester 11431;
PIC 290-5297;

6-Groove Pulley 55mm OD
 Clock Position 10

USED ON:
 2007-08 Ford Expedition w/5.4L
 2007-08 Lincoln Navigator w/5.4L

LI-RC-BVS Plug

REPLACES:
DENSO
 104210-5630;
FORD
 7L7T-10300-AC, 7L7Z-10346-B;
MOTORCRAFT
 GL-921;



VND0507
For Lexus, Toyota
IR/IF: 12-Volt: 150 Amp;
Remanufactured;
Lester 11352, 11765;
PIC 290-5397, -692;

8-Groove Pulley 54mm OD
 Clock Position 2

USED ON:
 2014-16 Lexus GX460 w/4.6L
 2010-12 Toyota Sequoia w/4.6L
 2008-16 Toyota Sequoia w/5.7L
 2010-16 Toyota Tundra Pickup w/4.6L
 2007-16 Toyota Tundra Pickup w/5.7L

REPLACES:
DENSO
 104210-5090, 104211-8641;
TOYOTA
 27060-0S020, -38110;



VND0518
For Ford Super-Duty
IR/IF: 12-Volt: 150 Amp;
Remanufactured;
Lester 11293;
PIC 290-5586;

6-Groove Pulley 59mm OD
 Clock Position 10

USED ON:
 2009-10 Ford F250, F350 Super-Duty Trucks w/5.4L, 6.8L
 2009-12 Ford F450, F550 Super-Duty Trucks w/6.8L

REPLACES:
DENSO
 104210-5820, -1;
FORD
 9C3T-10300-AB, -AC,
 9C3Z-10346-A;
MOTORCRAFT
 GL-959;



VND0541
For Buick, Cadillac
IR/IF: 12-Volt: 150 Amp;
Remanufactured;
Lester 11178;
PIC 290-5082D, -E;

6-Groove Pulley 62mm OD
 Clock Position 7

USED ON:
 2006-11 Cadillac DTS w/4.6L
 2006-11 Buick Lucerne w/4.6L

Small L-F Plug
 Super RVC

REPLACES:
DENSO
 104210-4370, -5990;
GENERAL MOTORS
 20843302, 25755840;



VND0590
For Ford
IR/IF: 12-Volt: 155 Amp;
Remanufactured;
Lester 11628;
PIC 290-5662;

8-Groove Pulley 62mm OD Single Alternator System
 Clock Position 11

USED ON:
 2011-16 Ford F-Series Pickups w/6.7L Dsl
 2011-15 Ford F-450 / 550 Super-Duty w/Ford 6.7L V8 Dsl

REPLACES:
DENSO
 104210-2920;
FORD
 BC3T-10300-CA,
 BC3Z-10346-B;
MOTORCRAFT
 GL-993;



VND0635
For Acura, Honda
IR/IF: 12-Volt: 120 Amp;
Remanufactured;
Lester 11604;
PIC 290-5628;

7-Groove Pulley 59mm OD
 Clock Position 10

USED ON:
 2013-15 Acura ILX w/2.4L
 2012-15 Honda Civic w/2.4L
 2012-14 Honda CR-V w/2.4L

Single LIN Plug

REPLACES:
DENSO
 104210-1530;
HONDA
 31100-RX0-A01, CSJ53;

GOLF CARTS



GCM0001
For EZ-Go
Golf Cart Motor;
36-Volt;

USED ON:
1995-07 EZ-Go Golf Carts w/36-Volt Series Electric Motors

REPLACES:
EZ-GO
73124G03;
GENERAL ELECTRIC
5BC48JB1061, D297;
ADVANCED MOTORS &
DRIVES
BD4-4001;

MARINE



AMT0301
For Volvo
IR/IF; 12-Volt; 90 Amp;
PIC 203-5369;

8-Groove Pulley 71mm OD

USED ON:
Volvo Applications

REPLACES:
MITSUBISHI
A4TR5392;
VOLVO
20466316;



SDR0435
For PG260L Series
PMGR; 12-Volt;
CCW; 11-Tooth;
Lester 6982;
PIC 140-6003;

PMGR Replacement for Delco 10MT Starter (Lester 6439:)

USED ON:
Marine Applications

REPLACES:
N/A

OUTDOOR POWER EQUIPMENT



420-44003
For Yamaha Golf Carts
12-Volt; 22 Amp;
Reversible;
Lester 15425;
PIC 304-101;

USED ON:
1985-95 Yamaha G2, G8, & G9-14 Applications

REPLACES:
HITACHI
GSB107-06B, J38-81100-11-00;
YAMAHA
J38-81100-00, -10, -11, -11-00;



420-46000
For Club Car
12-Volt; 25 Amp;
Reversible;
Lester 15435;
PIC 308-101;

USED ON:
1984-96 Club Car DS Series
1984-96 Club Car FE290
1984-96 Club Car FE350

REPLACES:
CLUB CAR
1018294-01;
MANDO
M063686;
VALEO
TMC000A0011, -1B0011;



420-46001
For Club Car
12-Volt; 25 Amp;
Reversible;
Lester 15404;
PIC 308-102;

USED ON:
Club Car Applications

REPLACES:
CLUB CAR
1018337-01;
MANDO
G096503, G278441, G338771;
VALEO
TMC000A0021;

POWERSPORTS



ABW6003
Voltage
Regulator / Rectifier
12-Volt;
For BMW M/C

90mm L x 80mm W x 28mm T
Plug #1 - (2) Green (B-), (2) Red (B+) Wires - 16 Inches Long
Plug #2 - (3) Yellow Wires - 16 Inches Long
Oblong Mounting Holes 88.4mm (Outer), 50.15mm (Inner)

USED ON:

2006-12 BMW F650GS w/650cc	2012-15 BMW F800GT w/800cc
2006-07 BMW F650GS Dakar w/650cc	2006-13 BMW F800R w/800cc
2012-15 BMW F700GS w/700cc	2007-09 BMW F800S w/800cc
2008-15 BMW F800GS w/800cc	2007-12 BMW F800ST w/800cc
2012-15 BMW F800GS Adventure w/800cc	2008-15 BMW G650GS w/650cc

REPLACES:

SHINDENGEN
SH541G-12;
BMW
61-31-2-346-550;



AHA6104
Voltage
Regulator / Rectifier
12-Volt;
For Honda M/C

110mm L x 85mm W x 38.5mm T
2 Plugs
Wire Loom and Plugs 10 Inches Long

USED ON:

2002-03 Honda VFR800 Interceptor w/781cc
2002-03 Honda VFR800A Interceptor ABS w/781cc

REPLACES:

HONDA
31600-MCW-D01;



AHA6107
Voltage
Regulator / Rectifier
12-Volt;
For Honda M/C

USED ON:

1985-87, 1996-00 Honda CMX250C Rebel w/234cc
1999-00 Honda CMX250C2 Rebel w/234cc
1986 Honda CMX250CD w/234cc

REPLACES:

SHINDENGEN
SH535A-12, -C-13
HONDA
31600-KR3-670, -71, -90;



ASU4024
Stator Coil
For Suzuki M/C

ID 37.4mm	# Posts 18
OD 107.0mm	Mounting Holes 3 - 6mm
Width (OD) 13.7mm	Cord Length 23 Inches (1 Plug)
Width (ID) 8.5mm	Cord Length 5 Inches (To Grommet)

USED ON:

2006-10 Suzuki GSX-R600 w/599cc
2006-10 Suzuki GSX-R750 w/749cc

REPLACES:

SUZUKI
31401-01H00, -10;



ASU4026
Stator Coil
12-Volt;
For Suzuki M/C

ID 53.5mm	OD 115.6mm
Width (OD) 29.3mm, (ID) 20.2mm	
# Posts 18	Mtg. Holes 3 - 6.4, 4 - 4.81

w/Pickup Coil
Cord Length 24 inches (1 Main Plug and 1 Pickup Plug)
Cord Length 5 inches (Clamp on Stator To Grommet)
Cord Length Pickup Coil 1.75 inches

USED ON:

2005-09 Suzuki VL1500 C90 Boulevard Cruiser w/1462cc
2005-09 Suzuki VL1500T C90T Boulevard Touring w/1462cc

REPLACES:

SUZUKI
32101-10F10, -11;

POWERSPORTS



AVA0180
For Polaris UTV
IR/IF; 12-Volt; 90 Amp;

1-V Pulley 69mm OD 8mm Bottom Mtg. Holes
13mm Belt Top Hole 8mm x 1.25
8mm B+ Stud

USED ON:
2013-14 Polaris Brutus 900 Diesel w/904cc

REPLACES:
VALEO
A000V611085;
POLARIS
4013427;



ESP2467
Voltage
Regulator / Rectifier
12-Volt;
For Yamaha ATV

94mm L x 80mm W x 27mm H
Espel Brand

USED ON:
2012-13 Grizzly 300 YFM300

REPLACES:
YAMAHA
1SC-H1960-00-00,
-01-00;



ESP2484
Voltage
Regulator / Rectifier
12-Volt;
For Honda M/C

94mm L x 80mm W x 27mm H
Espel Brand

USED ON:
2003-06 Honda CBR600RR

REPLACES:
HONDA
31600-MEE-003, -872;
SHINDENGEN
SH678-FA;



ESP2499
Voltage
Regulator / Rectifier
12-Volt;
For Suzuki M/C

90mm L x 80mm W x 28mm H
Espel Brand

USED ON:
1985 Suzuki GV700GLF Madura w/700cc
1985-86 Suzuki GV1200 Madura w/1165cc

REPLACES:
SHINDENGEN
SH541-12;
SUZUKI
32800-05A00;



ESP2500
Voltage
Regulator / Rectifier
12-Volt;
For Suzuki M/C

80mm L x 70mm W x 28mm H
Espel Brand

USED ON:
1990-93 Suzuki VX800
1997-04 Suzuki VZ800 Marauder

REPLACES:
SHINDENGEN
SH535C-12;
SUZUKI
32800-45C00, -1;



ESP2501
Voltage
Regulator / Rectifier
12-Volt;
For Honda M/C

90mm L x 80mm W x 28mm H
Espel Brand

USED ON:
1988-91 Honda NT650 Hawk GT

REPLACES:
HONDA
31600-MN8-008, -18, -28;
SHINDENGEN
SH538C-12;

POWERSPORTS



ESP2504
Voltage
Regulator / Rectifier
12-Volt;
For KTM M/C

90mm L x 80mm W x 28mm H
Espel Brand

USED ON:
2008-13 KTM 690 Enduro
2010 KTM 690 Enduro R
2008-10 KTM 690 SMC
2011 KTM 990 SMR
2008-09 KTM 950 Super Enduro R
2005-07 KTM 950 Supermoto
2010 KTM 990 Supermoto R/T

REPLACES:
KTM
62511034000, -100;
SHINDENGEN
SH541KF, -SB;



ESP2508
Voltage
Regulator / Rectifier
12-Volt;
For Suzuki M/C

107mm L x 80mm W x 28mm H
Espel Brand

USED ON:
2002-12 Suzuki DL1000 V-Strom

REPLACES:
SUZUKI
32800-06G00, -1, -2;



ESP2510
Voltage
Regulator / Rectifier
12-Volt;
For Triumph M/C

107mm L x 80mm W x 28mm H
Espel Brand

USED ON:
2008-17 Americana EFI w/865cc
2002-07 Americana Carb w/790cc
2008-17 Bonneville T100 w/865cc
2002-05 Bonneville T100 Carbs w/865cc
2008-17 Bonneville EFI w/865cc
2006-17 Scrambler EFI w/865cc

REPLACES:
TRIUMPH
T1300819, -88, -89;
2006-08 Scrambler Carb w/865cc
2002-07 Speedmaster Carbs w/865cc
2007-17 Speedmaster EFI w/865cc
2008-17 Thruxton 900 EFI
2000-03 TT600 w/600cc



ESP2511
Voltage
Regulator / Rectifier
12-Volt;
For Kawasaki, Suzuki
M/C

76mm L x 47mm W x 28mm H
Espel Brand

USED ON:
2004-On Kawasaki KLX400 R / SR
2000-04 Suzuki DR-Z400
2004-07 Suzuki DR-Z400E
2000-15 Suzuki DR-Z400S
1998-99 Suzuki RM250X

REPLACES:
KAWASAKI
21066-S005;
SUZUKI
32800-08D00, -29F00;
SHINDENGEN
SH572E-12;



SMU0308
For Yamaha M/C
PMDD; 12-Volt;
CCW; 9-Splines;
Lester 18764, 18770;
PIC 191-227, -384;

USED ON:
2001-05 FZ1 w/998cc
1998-99 YZF-R1 w/998cc

REPLACES:
YAMAHA
4XV-81800-00-00,
4XV-81890-00-00;



SMU0442
For Suzuki M/C
PMDD; 12-Volt;
CW; 9-Splines;
PIC 191-615;

USED ON:
2008-09 VLR1800 C109 Boulevard Cruiser w/1783cc
2008-09 VLR1800T C109RT Boulevard Touring w/1783cc
2006-13 VZR1800 M109R Boulevard Cruiser w/1783cc
2014-17 VZR1800BZ M109R Boulevard Cruiser w/1783cc
2006-09 VZR1800N M109R Boulevard Cruiser w/1783cc
2006-13 VZR1800Z M109R Boulevard Cruiser w/1783c

REPLACES:
SUZUKI
31100-48G00;

POWERSPORTS



SMU0445
For Yamaha M/C
PMDD; 12-Volt;
CW; 9-Splines;
PIC 191-513;

USED ON:
2006-15 FX10S FZ1 w/998cc

REPLACES:
YAMAHA
2D1-81890-00-00;



SMU0449
For Yamaha M/C
PMDD; 12-Volt;
CCW; 9-Spline;
PIC 191-593;

Gear Length 30.3mm (From Bearing Surface)

USED ON:
2008-18 TTR110E w/110cc

REPLACES:
YAMAHA
5B6-H1800-00-00,
-01-00;



SMU0475
For Honda M/C
PMDD; 12-Volt;
CCW; 9-Spline;
PIC 191-560;

USED ON:
2009-17 CBR600RA w/599cc
2007-17 CBR600RR w/599cc

REPLACES:
HONDA
31200-MFJ-D01;



SMU0526
For Yamaha
Snowmobiles
PMDD; 12-Volt;
CCW; 9-Spline;
PIC 190-6092;

USED ON:
2007-09 Phazer FX PZ50 w/499cc
2007-13 Phazer GT PZ50GT w/499cc
2007-08 Phazer Mountain Lite PZ50MT w/499cc
2009-14 Phazer MTX PZ50MT w/499cc
2007-08 Phazer PZ50 w/499cc
2008-14 Phazer RTX PZ50RT w/499cc
2014 Phazer XTX PZ50XT w/485cc
2007-13 Venture Lite PZ50 w/499cc
2013 Venture Multi Purpose PZ50M w/499cc

REPLACES:
YAMAHA
8GC-81890-00-00,
-01-00;



SMU0559
For Honda M/C
PMDD; 12-Volt;
CCW; 9-Spline;

USED ON:
2013-17 CB500F, -FA w/471cc
2013-17 CBR500R, -RA w/471cc

REPLACES:
HONDA
31200-MGZ-J01;



SMU0569
For Polaris ATV, UTV
PMDD; 12-Volt;
CW; 9-Spline;

USED ON:
2014-15 Sportsman 325 ACE EFI w/325cc ATV
2015 Sportsman ETX EFI w/30HP ATV
2015 Sportsman ETX EFI HD w/30HP ATV
2015 Hawkeye 325 2x4 w/325cc ATV
2015 Ranger ETX w/31HP UTV

REPLACES:
POLARIS
4013428, 4014972,
4015223;

POWERSPORTS



SMU6183
Solemoid, Remote
12-Volt;
For Yamaha UTV

Fits Many Models
10A Fuses
Battery Terminal on Lower Left Side

USED ON:
2008-13 Rhino 700 YXR700F w/686cc
2014-15 Viking 700 YXM700D w/686cc
2014 Viking 700 EPS YXM700P w/686cc
2015 Viking 700 EPS YXC700P w/686cc
2015 Viking 700 EPS YXM700P w/686cc

REPLACES:
YAMAHA
5B4-81940-00-00, 5S7-
81940-00-00;



SSE6018
Starter Relay
12-Volt;
For Arctic Cat
Snowmobiles,
Toro Lawn Tractors

Main Studs 1/4-20 Ground Stud 8-32
Ignition Stud 8-32

USED ON:
2013-17 Arctic Cat Snowmobiles (Many)
Toro Lawn Tractors (Many)

REPLACES:
TROMBETTA
772-1221-212;
ARCTCO
0645-673;
TORO
106-8245;

COMPONENTS



AMT6113TR
Voltage
Regulator w/Brushes
For Ford Escape,
Mazda Tribute,
Mercury Mariner
PIC 8003-3133;

Main Studs 1/4-20 Ground Stud 8-32
Ignition Stud 8-32

USED ON:
Lester 11271, 11272, 11411, 11684, 12878;

REPLACES:
N/A



AND1652
Insulator, B+ Stud
Denso Alternators

13.8mm ID;
USED ON:
Denso Alternators

REPLACES:
N/A

WE KEEP YOU RUNNING 

MAIN LOCATION

CALL: (800) 328-5454
FAX: (763) 255-2530
3787 95th Ave. NE
Blaine, MN 55014

WEST COAST

CALL: (800) 457-1728
FAX: (209) 537-2856
821 Oates Court
Modesto, CA 95358

CANADA

CALL: (877) 617-2888
FAX: (416) 645-1972
398 Canarctic Drive
North York, Ontario M3J 2V3

The information herein is based upon data which we believe to be correct and believe to have been obtained from reliable sources, but no representation is made herein, nor should any be implied, regarding the accuracy of any such information and we assume no liability for any errors or omissions in any such information. Any original equipment manufacturers or other manufacturers or distributors, whose names, numbers, pictures, symbols, products and/or descriptions are, or may be, listed or shown herein are used for reference purposes only and there is no representation made or intended, nor should any be implied, that any item reference herein is the product of, or was manufactured and/or distributed, by, the referenced manufacturer or distributor, as the case may be. This brochure is intended for reference purposes only. For pricing or terms and conditions, please refer to your price sheet.