

NEW PRODUCTS

MAIN LOCATION 800.328.5454 | EAST COAST 855.214.0712 | WEST COAST 800.457.1728 | CANADA 877.617.2888

AG / INDUSTRIAL



AIA0030
For AGCO,
Massey Ferguson
IR/EF; 12-Volt;
80 Amp;
Lester 12697;
PIC 282-536;

2-V Pulley 70mm OD

USED ON:
AGCO Tractors
2002-04 RT115, -4WD w/Cummins 6-359
2002 RT95 w/Cummins 6-359
AGCO Challenger Farm Tractors
2004-08 MT425B / MT445B / MT455B / MT465B w/Caterpillar 4-269
2004-07 MT525B / MT545B w/Caterpillar 6-365
2002-04 MT535 / MT545 w/Caterpillar 6-365
2004-08 MT535B w/Caterpillar 6-365
2007-08 MT545B w/AGCO 6-403 Dsl
Massey Ferguson MF4245, MF4250

REPLACES:
LETRIKA IA 0984;
AGCO 3821974M91,
-5M91, 82036252;
MAHLE MG539;
MASSEY FERGUSON
3821974M91, -5M91;



AVA0122
For Bobcat
IR/IF; 12-Volt;
80 Amp;
Lester 11736;
PIC 208-989;

1-V Pulley 69mm OD
Clock Position 3

USED ON:
Bobcat Skid Steer Loaders
2000-08 463 w/Kubota D1005-E2B
2000-07 553F w/Kubota D1105 Dsl
2008-13 S70 w/Kubota D1005-E2B

REPLACES:
VALEO
A002655302;
BOBCAT
6678560, -R;



GB00002
For Intermotor
Engines, Etc.
Generator
12-Volt; CW;
PIC 320-51;

USED ON:
1972-00 BCS Lawn Mowers
1972-81 Goldoni Modial 107
1978-83 Goldini Motocoltivatore 611
1978-80 Hako Hamster S

1975-ON Intermotor Engines
1968-80 Lombardini Engines
1967-87 Piaggio APE

REPLACES:
BOSCH
0-010-300-002, -004,
-006, -100;



SB00330
For Hyster Lift
Trucks
DD; 12-Volt;
CW; 10-Tooth;
Lester 18035;
PIC 120-545;

Wet Clutch
USED ON:
Hyster w/ Perkins Engine

REPLACES:
BOSCH
0-001-367-054;
HYSTER
135125, 3042511,
326460, 345433;

AUTO



AMT0308

For Ford
IR/IF; 12-Volt;
190 Amp;

6-Groove Decoupler Pulley 54.5mm OD
Clock Position 12
AMT0126 w/OE Litens Decoupler Pulley

USED ON:
2003-11 Ford Crown Victoria (Police) w/4.6L

REPLACES:
MITSUBISHI A4TJ0181, -ZC;
FORD
4W73-10300-AC, 4W7Z-10346-AC,
FW73-10346-AC, 6W7T-10300-AB,
6W7Z-10346-AA;
MOTORCRAFT GL -598, -671;



AVA0169

For Nissan
IR/IF; 12-Volt;
110 Amp;

6-Groove Clutch Pulley 49mm OD
Clock Position 10

USED ON:
2013-16 Nissan Sentra w/1.8L

REPLACES:
VALEO
FG12T039;
NISSAN
23100-3SH2B;

Lester 11673;
PIC 208-058;



SND0795

For Ford, Lincoln
PMGR; 12-Volt;
CW; 12-Tooth;
Lester 19247;
PIC 190-925;

USED ON:
Ford
2014 E-Series Vans w/4.6L V8, 5.4L V8, 6.8L V10
2014 Expedition w/5.4L V8
2014-16 F-150 w/5.0L V8
2014 F-150 w/6.2L V8
2014-16 F-250 / 350 Super Duty w/6.2L V8
2013-15 F-450 / 550 Super Duty w/Ford 6.8L V10 Gas
Lincoln
2014 Navigator w/5.4L V8

REPLACES:
DENSO
438000-0410, -2930;
FORD
DL3T-11000-AA, -BA,
DL3Z-11002-A, -B;
MOTORCRAFT
SA-1026;



SND0799

For BMW
PMGR; 12-Volt;
CW; 13-Tooth;
Lester 19248;
PIC 190-927;

USED ON:
BMW
2014-15 335 Series w/3.0L
2014-16 435 Series w/3.0L
2014-16 535 Series w/3.0L
2011-16 640 Series w/3.0L
2013-15 740 Series w/3.0L
2014-16 M235i w/3.0L
2014-16 M3 w/3.0L
2014-16 M4 w/3.0L
2011-16 X3 w/3.0L
2014-16 X4 w/3.0L
2012-16 X5 w/3.0L
2014-16 X6 w/3.0L
2015-16 X6 w/3.0L

REPLACES:
DENSO
428000-9130;
BMW
12-41-7-631-558, 9;



SND0800

For Ram
PMGR; 12-Volt;
CW; 13-Tooth;
Lester 32567;
PIC 190-975;

Trucks w/Start-Stop Feature
USED ON:
2014 Ram 1500 w/5.7L V8
2014-15 Ram 3500 w/5.7L V8

REPLACES:
DENSO
438000-0330;
CHRYSLER
56029652AA;



SND0801

For Land Rover
PMGR; 12-Volt;
CW; 11-Tooth;
Lester 30242;
PIC 180-493;

USED ON:
2015-16 Discovery Sport w/2.0L
2013-15 LR2 w/2.0L
2012-16 Range Rover Evoque w/2.0L

REPLACES:
DENSO
428000-8420, -1;
FORD
BJ21-11001-AB, -AC, BJ32-11001-AC;
LAND ROVER
LR028120, -31028, -44091, -47574;

AUTO



SND0815
For Porsche
PMGR: 12-Volt;
CW: 13-Tooth;
PIC 120-673;

USED ON:
Porsche
2012-16 911 Series w/3.4L, 3.8L
2013-15 Boxster w/2.7L, 3.4L
2014-16 Cayman w/2.7L, 3.4L

REPLACES:
DENSO
428000-8700, -1;
PORSCHE
9A1-604-109-00, -X;

HD TRUCKS



AMT0311
For Mitsubishi
Industrial
IR/EF: 24-Volt;
40 Amp;
Lester 12315;
PIC 203-280;

Clock Position 3
USED ON:
1992-98 Mitsubishi Fuso (Canter) w/5.0L T Dsl

REPLACES:
MITSUBISHI
A4T58285, -289, -686, -689, -699,
-986, -987, -989, -999;
MITSUBISHI INDUSTRIAL
ME049194, ME077138, ME087566,
-643, ME090198, -591, -592,
ME091535, ME150142;

MARINE



AMR6006
Voltage
Regulator / Rectifier
12-Volt;
For Mercury, Yamaha

88.6mm L x 80mm W x 28mm T
Plug - (3) Green Wires w/Round Plug 168mm OAL
(1) Red Wire w/Male Bullet 138mm OAL
(1) Black Wire w/Eyelet 172mm OAL
USED ON:
Mercury 75-90HP 4-Stroke
2000-05 Yamaha 80-100HP Outboard

REPLACES:
SHINDENGEN
SH758AA;
MERCURY MARINE
804278A12, 804278T11;
YAMAHA
67F-81960-10-00, -11-00, -12-00;

POWERSPORTS



ACH0002
For John Deere UTV
IR/IF: 12-Volt;
65 Amp;

Clock Position 12
USED ON:
All Gator XUV 590i, -S4 w/32HP 586cc

REPLACES:
JOHN DEERE
MIA13192;



IPO6006
CDI Module
For Polaris ATV, UTV
Capacitive
Discharge Ignition

USED ON:
ATV
2004 ATP 500 HO 4x4 w/499cc
2002 ATV Pro 500 4x4 PPS w/499cc
2002-03 Magnum 500, -HDS w/499cc
2003-04 Sportsman 400 w/425cc
2002-04 Sportsman 500 HO w/499cc

REPLACES:
POLARIS 3087169;
UTV
2002 Big Boss 500 6X6 INT'L w/499cc
2003 Ranger 6X6 w/499cc
2002-03 Sportsman 500 6x6 w/499cc
And Many More

POWERSPORTS



IPO6009
CDI Module
 For Polaris ATV, UTV
Capacitive Discharge Ignition

USED ON:
 ATV
 2005 ATP 500 HO 4x4 w/499cc
 2007-09 Hawkeye 300 2x4 w/299cc
 2007-09 Scrambler 500 2x4 Intl w/499cc
 2004-09 Scrambler 500 4x4 w/499cc
 2004-05 Sportsman 400 w/425cc

REPLACES:
POLARIS 3089238;
 UTV
 2005-09 Ranger 2X4 500 w/499cc
 2004-07 Ranger 4X4 500 w/499cc
 2004-08 Sportsman 500 6x6 w/499cc
 And Many More



IYA0010
Ignition Coil
 12-Volt;
 For Yamaha ATV

USED ON:
 2000-12 Big Bear 400 4WD YFM400F w/386cc

REPLACES:
YAMAHA 5FU-82310-00-00;



SMU6148
Solenoid, Remote
 12-Volt;
 For KTM ATV, M/C

Battery Stud on Right Front
 Fits Many Models

10 Amp Fuses

REPLACES:
KTM 58211058000;

USED ON:
 1999-15 KTM ATV, M/C



SMU6174
Solenoid, Remote
 12-Volt;
 For Honda ATV

19 Inch Wires
USED ON:
 2007-08 TRX300EX w/281cc
 2009 TRX300X w/281cc

REPLACES:
HONDA 35850-HM3-A60;



SMU6176
Solenoid, Remote
 12-Volt;
 For Honda M/C

15 Amp Fuse
USED ON:
 2005-16 CRF450X w/449cc

REPLACES:
HONDA 35850-KCN-000, -3;

WE KEEP YOU RUNNING



MAIN LOCATION

CALL: (800) 328-5454
FAX: (763) 255-2530
 3787 95th Ave. NE
 Blaine, MN 55014

EAST COAST

CALL: (855) 214-0712
FAX: (508) 857-0586
 145 Bodwell Street
 Avon, MA 02322

WEST COAST

CALL: (800) 457-1728
FAX: (209) 537-2856
 821 Oates Court
 Modesto, CA 95358

CANADA

CALL: (877) 617-2888
FAX: (416) 645-1972
 398 Canarctic Drive
 North York, Ontario M3J 2V3